



Photo 1 – View of fuselage damage (photo courtesy of the FAA)



Photo 2 - View of empennage damage (photo courtesy of the FAA)



Photo 3 - View of right wing damage (photo courtesy of the FAA)