

DOCKET NO. **SA-516**

EXHIBIT NO. **21P**

**NATIONAL TRANSPORTATION SAFETY BOARD  
WASHINGTON, D.C.**

**Appendix 15: Exempt 2000 - Series Tags  
(9 pages)**

**Appendix 15: Exempt 2000-series tags**

Exempt 2000 tags

Tag #	Job #	Description (Actual)	Disposition/Comments
A2031	RF21	body crown fuselage	LOT# UPDATED PER 2000 SERIES AUDIT; CHANGED FROM B561 TO MATCH ACTUAL DEBRIS FIELD
A2037		floor beam with fiberglass floor panel #101, FS 860-880, RBL 55-76,	LOT# UPDATED PER 2000 SERIES AUDIT; "ENTANGLED IN WIRES ASSOCIATED W/ A004"; RED BUT CANNOT CONFIRM SOURCED FROM TGT DBASE
A2038		seat 19 (1 2 3)	
A2041		seat 12 (8) armrest	SOURCED FROM TGT DBASE
A2048	LF14A, LF55D	keel beam section box, also refer to LF 55D, LF55D = bulkhead intercostal segment under wing, front door spar	PART OF VALID TAG (B061), WHICH WAS CHANGED TO GREEN FIELD; SEE DOCUMENTATION; SOURCED FROM EXEMPT; SEE DOCUMENTATION
A2054	CW911	CW SWB #1 section	
A2068	RF35	right side fuselage with letters "TR" S6R-19R FS 855-960	CUT FROM VALID TAG, A421
A2070	LF162-1	cargo floor beam with roller track cut from LF162 at FS 800 LBL20-RBL11	CUT FROM VALID TAG
A2071	FBM30	segment of wing beam FS 1090 LBL 57	
B2021	RF18D	FS 460-520 STR 31R-38R	LOT# UPDATED PER 2000 SERIES AUDIT; REMOVED FROM VALID TAG A223
B2049	LF190	FS 580-600 skin, was part of B060 cargo floor with wheels	FORMERLY B163, THEN B163A, RENAMED TO B202; THE 2 WL SOURCE TAGS B169 AND B141 ARE INAPPROPRIATE
B2068	LF19B	part of LF19A; saw cut separated part into two pieces	LOT# UPDATED PER 2000 SERIES AUDIT; REMOVED FROM VALID TAG, B060
C2147	CW201	lower CW skin, RH FWD STR 1-21	LOT# UPDATED PER 2000 SERIES AUDIT; REMOVED FROM VALID TAG, B265
C2151	CW104, CW301,	upper RH FWD CW skin, double plus chord, STR 19-30, also a part of RH SOB CW rib (CW301), also upper CW skin	CUT FROM C108
C2255	LF10B	part aft press bulkhead FS 2360	PHOTO ID ON GRASP; SEE DOCUMENTATION
C2278	RF17	right hand body attached to right hand upper wing with 3R door opening; 1 of 3 tags - see also C2279 (CW302), C2280	SOURCE TAG C167 NOT IN FBI LOG, BUT PART IS ASSOCIATED WITH IT (SEE PART)
C2279	CW302	#2 of 3 on same piece RH CW upper SOB rib	SAME PART AS C183 (NOT CUT)
C2280	CW1001	#3 of 3 tags on same piece RH CW rear spar	SAME PART AS C183 (NOT CUT)

Tag #	Log #	Description (Actual)	Validation Comments
C2320		seat 23 (2 3); seat 23 (1) armrest	LOT# UPDATED PER 2000 SERIES AUDIT; L/L FROM BOAT TAG ON PART
C2331	RF9A	FS 1900-2320 STR 10L-6R; saw cut from RH side for RF9B and RF15	CUT FROM VALID TAG, C117
C2332	RF9B	FS 1900-2140 STR 6R-22R with window note: saw cut from RF 9A and RF15	CUT FROM VALID TAG, C117
C2349	RF44E	FS 2060-3000 STR 29R-36R	NO LOT#; SOURCED FROM C123; SEE WL'S
C2364		seat 44 (6)	SEPARATED FROM C116 GROUP
C2365		seat 45 (6 7)	SEPARATED FROM C116 GROUP
C2366		seat 51 (6) armrest, cap, and tray table	SEPARATED FROM C116 GROUP
C2367		seat 42 (6 7)	SEPARATED FROM C116 GROUP
C2402	CW1101	CW BBL 0 rib, from mid spar AFT 20", from upper rib chord down 36"	POSIT FROM BOAT LABEL ON PART
C2447	CW704B	SWB #2 RBL 11 stiffener	LOT# UPDATED PER 2000 SERIES AUDIT; SEE DOCUMENTATION; USE ORIG. B003 TAG, CHANGED TO
C2448	CW704A	SWB #2, RBL 33-3	SEE REPORT CW704.DOC; USE ORIG. B003 TAG, CHANGED TO GREEN FIELD, AS SOURCE. SEE DOCUMENTATION
C2449	CW721	SWB #2 upper chord, web RBL 11.33	TARGET LISTED ON PAPER TAG BY NYPD
C2460	RF126	wheel well pressure deck FS 1330-1241	PHOTO ID W/ C109
C2461	RF126-1	floor beam part of RF126, part cut from RF126	PHOTO ID W/ C109
C2463	RF42-1	section cut from RF42	CUT FROM VALID TAG, C845
C2464	RF119	right body gear bulkhead FS 1480; part removed from C105	LOT# UPDATED PER 2000 SERIES AUDIT; CUT FROM VALID TAG, C105
C2468	LF92	left body landing gear trunnion; removed from C104 LG3	LOT# UPDATED PER 2000 SERIES AUDIT; CUT FROM VALID TAG, C104
C2470	LF156	FS 1480 bulkhead LBL 51 WL 126, removed from LG3 C104	CUT FROM VALID TAG, C104

W

Tag #	Tag #	Description (Actual)	Valuation Comments
C2471	LF157	FS 1480 pressure bulkhead LBL 33 WL 107.7, note: removed from LG3 104	CUT FROM VALID TAG, C104
C2472	LF158	FS 1480 pressure bulkhead LBL 19 WL 117.8, note: removed from LG3 C104	CUT FROM VALID TAG, C104
C2473	RF10A	fuselage right side, cut at FS 1630 from RF10A; see also C106	CUT FROM VALID TAG, C106
C2474	RF10A	fuselage right side, cut at FS 1630 from RF10A; see also C106	CUT FROM VALID TAG, C106
C2476	LF14L	LG3 drag strut fitting on keel beam	CUT FROM VALID TAG, C104
C2479	LF14C	keel beam left side FS 1152-1255	EXEMPT; SEE DOCUMENTATION
C2480	LF14C	keel beam left side FS 1235-1255	EXEMPT; SEE DOCUMENTATION
C2481	LF14B, CW1009,	keel beam box, sooted section	EXEMPT - SEE DOCUMENTATION
C2482	LF161	floor beam LBL 33.99 frame FS 1295-1339	BROKE FROM CONFIRMED PART, C2460
C2485	LF16B-1	sloping pressure deck FS 1240 aft LBL 11.33-22.55	CUT FROM VALID TAG C2136; USE THAT TAG'S SOURCE
C2486	LF92-1, LF151	left body landing gear trunnion support fitting LBL 64, note removed from C104 LG3	CUT FROM VALID TAG, C104
D2086	FBM14C	floor beam FS 840 LBL 21-33	POSIT FROM BOAT LABEL: L/L 40 38 34.72 / -72 38 28.27; NO LOT#; CHANGED FROM WHT TO RED PER 2000 SERIES
X2201	LF74	large section of metal (8'x6') changed from Z3453 to X2201 to match actual debris field	LOT# UPDATED PER 2000 SERIES AUDIT; CHANGED FROM Z3453 TO XX201 TO MATCH ACTUAL DEBRIS FIELD
Z2168	CW223	rear spar CW at RBL 127	CUT FROM VALID TAG, C256
Z2395		piece of debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2396		AR1054, big cylindrical object, #2 engine pc	LOT# REMOVED; ORIG TAG FROM BOAT
Z2397		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2398		debris	LOT# REMOVED; ORIG TAG FROM BOAT

4

Tag #	Log #	Description (Actual)	Valuation Comments
Z2399		paper and debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2400		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2532		removed tag from part tagged Z3125	LOT# REMOVED; ORIG TAG FROM BOAT
Z2551		vent 5'x6" diameter	LOT# REMOVED; ORIG TAG FROM BOAT
Z2552		various siding (bagged) , hydraulic framing	LOT# REMOVED; ORIG TAG FROM BOAT
Z2553		clothing	LOT# REMOVED; ORIG TAG FROM BOAT
Z2554		various siding (bagged)/ hydraulic framing	LOT# REMOVED; ORIG TAG FROM BOAT
Z2555		clothing	LOT# REMOVED; ORIG TAG FROM BOAT
Z2556		misc. siding	LOT# REMOVED; ORIG TAG FROM BOAT
Z2557		misc. siding	LOT# REMOVED; ORIG TAG FROM BOAT
Z2559		1 large piece of twisted metal, 1 window and seal, 1 small piece of twisted metal	LOT# REMOVED; ORIG TAG FROM BOAT
Z2563		misc. debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2564		misc. debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2565		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2566		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2567		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2568		bags, gray	LOT# REMOVED; ORIG TAG FROM BOAT
Z2569		toilet seat lid, life vest, debris	LOT# REMOVED; ORIG TAG FROM BOAT

5

Exempt 2000 tags

4/23/97

Tag #	Description	Disposition
Z2570	2 plastic bags, hatch, misc. metal pieces	LOT# REMOVED; ORIG TAG FROM BOAT
Z2571	1 gray plastic bag and misc. metal	LOT# REMOVED; ORIG TAG FROM BOAT
Z2572	duct work and metal	LOT# REMOVED; ORIG TAG FROM BOAT
Z2573	metal and pipe	LOT# REMOVED; ORIG TAG FROM BOAT
Z2574	plastic bag and air duct	LOT# REMOVED; ORIG TAG FROM BOAT
Z2575	H1 fuselage fragment or flight control surface or wing	LOT# REMOVED; ORIG TAG FROM BOAT
Z2576	debris, wing	LOT# REMOVED; ORIG TAG FROM BOAT
Z2577	rudder FS 57.8	LOT# REMOVED; ORIG TAG FROM BOAT
Z2578	debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2579	plastic gasket	LOT# REMOVED; ORIG TAG FROM BOAT
Z2580	debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2581	personal effects	LOT# REMOVED; ORIG TAG FROM BOAT
Z2582	debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2583	debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2584	debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2585	debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2586	LF69 crown skin FS 1241-1438 STR 5L-8R	LOT# REMOVED; ORIG TAG FROM BOAT
Z2587	debris	LOT# REMOVED; ORIG TAG FROM BOAT



Exempt 2000 tags

4/23/97

Tag #	Log #	Description (Actual)	Validation Comments
Z2588		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2589		pipes and debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2590		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2591		large pieces of debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2592		numerous pieces of debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2593		piece of debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2594		pipe, material (cloth), little piece of filter, debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2601		some kind of pipes with (TWA 15201/ s/n 237)	LOT# REMOVED; ORIG TAG FROM BOAT
Z2602		window, carpet, debris, human remains	LOT# REMOVED; ORIG TAG FROM BOAT
Z2603		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2604		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2605		fire extinguisher tanks and pipes, debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2606		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2607		human remains	LOT# REMOVED; ORIG TAG FROM BOAT
Z2608		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2609		window molding	LOT# REMOVED; ORIG TAG FROM BOAT
Z2610		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2611		large piece of debris	LOT# REMOVED; ORIG TAG FROM BOAT





Tag#	Log#	Description (Actual)	Validator Comments
Z2612		debris and miniature bottle	LOT# REMOVED; ORIG TAG FROM BOAT
Z2613		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2614		two pieces of debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2616		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2617		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2619		large fuel flange	LOT# REMOVED; ORIG TAG FROM BOAT
Z2620		bag of debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2621		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2623		mail envelope (white), piece of hose	LOT# REMOVED; ORIG TAG FROM BOAT
Z2624		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2625		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2633		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2634		strut 7' long 65B067617	LOT# REMOVED; ORIG TAG FROM BOAT
Z2635		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2636		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2637		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2638		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2639		debris in bag	LOT# REMOVED; ORIG TAG FROM BOAT

Exempt 2000 tags

4/23/97

Tag #	Lot #	Description (Actual)	Description (Consistent)
Z2640		book	LOT# REMOVED; ORIG TAG FROM BOAT
Z2641		debris and black bag of debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2642		#3 engine debris and black bag of debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2643		debris and black bag of debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2644		debris and black bag of debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2645		debris and black bag of debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2646		book	LOT# REMOVED; ORIG TAG FROM BOAT
Z2647		fuel pipe	LOT# REMOVED; ORIG TAG FROM BOAT
Z2648		strapped gray mass unknown (mail?)	LOT# REMOVED; ORIG TAG FROM BOAT
Z2649		debris	LOT# REMOVED; ORIG TAG FROM BOAT
Z2664		seat 34 (7) armrest	LOCATED IN TGT DBASE
Z2665		seat 32 (4 5) armrest and frame	LOCATED IN TGT DBASE
Z2742	FBM31A	floor beam FS 960 RBL 101-SOB on right hand side	LOT# UPDATED PER 2000 SERIES AUDIT; ORIG TG6; USE L/L FROM THAT TAG
Z2761		cargo deck roller, red encased- piece of tubing joint, small green tubing, green plastic, misc. wires, small metal debris	LOT# UPDATED PER 2000 SERIES AUDIT; ORIG TAG FROM BOAT
Z2789		seat 32 (6)	LOCATED IN TGT DBASE
Z2836		seat 28 (9) cap and armrest pad	TRAWLER TAG
Z2837		seat 28 (0) armrest	TRAWLER TAG

9