

Photo 1 – View of BRS Parachute Risers Suspended in Trees Above Airplane Wreckage (Robinson)




Photo 2 – View of Airplane Wreckage as Found (Robinson)



Photo 3 – View of Severed Right Main Landing Gear Leg (Robinson)



Photo 4 – View of Intact Left Flap and Landing Gear (Robinson)



Photo 5 – View of Helicopter Wreckage as Found (Robinson)



Photo 6 – View of Helicopter Main Rotor Blade (Robinson)




Photo 7 – View of Tailboom, Tailrotor, and Main Rotor Blade (Robinson)



Photo 8 – View of Flap Selector Knob (Cirrus)