NATIONAL TRANSPORTATION SAFETY BOARD

EVIDENCE CONTROL

ACCIDENT NUMBER: CEN19LA111

For Use In All Modal Investigations						
OFFICE	DATE OF ACCIDENT	ACCIDENT LOCATION (City & State)				
Aviation Safety	3/26/19	Newton	KS			
EVIDENCE OBTAINED BY: E Malinowski						
EVIDENCE OBTAINED FROM:	LOCATION OR PERSON INFORMATION E Malinowski on scene		DATE			
EVIDENCE RECEIVED FROM:			3/26/19			
EVIDENCE CONTROL NUMBER			GROUP			
CEN19LA111 - PWR - 1			Powerplant			
DESCRIPTION (☐ BIN ITEM - <i>HAS BEEN SEPARATED</i> ☐) Continental Engine C85-12 sn 23193-6-12						

OWNER OR OWNER'S REPRESENTATIVE						
FIRST NAME:			LAST NAME:			
В.			Patton			
ADDRESS: WICHITA, KS 67204-2357						
PHONE:		EMAIL:				
RETURNED 🛛	DATE: 8/22/19	CONTACT: Mr. Patton				
CHAIN OF CUSTODY						
RELEASED BY: M	. Ammerman, Midwest	RELEASED Bonding D	DATE: 4/18/19			
PURPOSE: Examination at Continental Motors via YRC Pro#						
RELEASED BY: E. Malinowski at Continental		RELEASED TO: Midwest Aircraft Services		DATE: 8/22/19		
PURPOSE: Returned to Midwest Aircraft Services Inc. via FedEx #						
RELEASED BY: ***********************************		RELEASED TO: ***********************************		DATE:		
PURPOSE:						
RELEASED BY:		RELEASED TO:		DATE:		
PURPOSE:						
RELEASED BY:		RELEASED TO:		DATE:		
PURPOSE:						