Name, Date & Signature (h)

t pages ...

Date No. Landings (a) (b)	Airframe		Engine		Faults, comments, inspection or work carried out; list number or source of all parts	Name, Date
	hrs flown (c)	total (d)	hrs flown (e)	total (f)	fitted; an entry is to be made within 7 days for all occurences or work done (g)	& Signature (h)
from previous		(- /				
3/26/14				*	Replaced fuel pump As Pere Rotar Service Bulleting June 24, 2013 73-00-060. New pump, New gishet 11 stalled, bolts toregood, Lock tite plue. Motor tested With Molents. Gary C. Bezedenve Paul Aniation Factory Authorized Technickin "I certify that this aircraft N428PM has been inspected on April 1. 2014 in accordance with the scope and detail of appendix D to part 43 or the manufacturer's inspection procedures, and was found to be in a condition for safe operation." The aircraft's total time in service is: 179.1. The engine TT is: 179.1 hrs Wing TT is: 179.1 hrs Prop. TT is: 179.1 hrs Christopher Antoskow,	

aircraft pages ... aircraft aircraft aircraft aircraft aircraft aircraft aircraft aircraf