						Page No
DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME		CRIPTION OF WORK	PERFORMED— ERSON PERFORMIN	G WORK
		TOTAL br	NATIONAL AIR COLLEGE SAN DIEGO, CA	N1285U APR. 25, 2015	TACH: 2493.7 TTAF: 9754.7	
			SERVICED BATTERY. CLEANED INSPECTED AND LUBED FLIGH FLAPS. INSPECTED AND SERVIC INDUCTION FILTER BA-6108. R REPLACED OVER	T CONTROL HINGES CED BRAKES AND TI	, PULLEYS AND RES. REPLACED FILTER B3-5-1.	
-			C/W AD 2011-10-09 SEA VIA VISUAL INSPECTION OF F NEXT DUE			
			Authorized Signature			
			NATIONAL AIR COLLEGE SAN DIEGO, CA	N1285U JUN. 16, 2015	TACH: 2548.3 TTAF: 9809.3	
	ī		SECURED AIRBOX F	LAPPER VALVE TO	SHAFT.	
v						
			0.0		area 11D	<u></u>
			Authorized Signature	A defension of the second s		
			NATIONAL AIR COLLEGE SAN DIEGO, CA	N1285U JUN. 25, 2015	TACH: 2560.9 TTAF: 9821.9	
			REPLACED RIGHT SUPPLY 150-00	WING STROBE POV 07 AND BULB 73-027	VER 0	
			960 •			x
	F					ξ.
			Authorized Signature			
			NATIONAL AIR COLLEGE SAN DIEGO, CA	N1285U JUL. 26, 2015	ТАСН: 2588.1 ТТАF: 9849.1	
			SERVICED BATTERY. CLEANE INSPECTED AND LUBED FLIGI	HT CONTROL HINGE	S, PULLEYS AND	
			TREATED CORROSION IN TA			
	VACUUM SYSTEM FILTERS, LUBED PRIMER CONTROL O-RINGS. TREATED CORROSION IN TAIL WITH CORROSION X. REPLACED INDUCTION FILTER BA-6108. REPLACED GASCULATOR O-RINGS M83248/1-111 AND M93248/1-138. REPLACED ONE UPPER COWL MOUNT SK2003-14A.	E UPPER COWL	lan a linna a a dinimala			
4			(CONTINUED NEXT PAGE)			
¢.						
			AL this page arry forward to next page			

Page No.___

DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED – SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK				
		TOTAL br	(CONTINUED FROM PREVIOUS PAGE)				
			C/W AD 2011-10-09 SEATS AND RAILS INSPECTION VIA VISUAL INSPECTION OF FRONT SEATS AND SEAT TRACKS. NEXT DUE TACH: 2688.1.				
- 1)			I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH AN <u>ANNUAL INSPECTION</u> AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.				
			Authorized Signature				
			NATIONAL AIR COLLEGE N1285U TACH: 2608.1 SAN DIEGO, CA AUG. 14, 2015 TTAF: 9869.1	3			
	2		SERVICED NOSE STRUT WITH MIL-5606 HYDRAULIC FLUID. STOP DRILLED CRACK IN LEFT ELEVATOR UPPER SKIN.				
			Authorized Signature				
				D			
and a second		3					
		=	а а а				
55		X					
	-						
				y.			
		-	TAL this page				