



Tank car AXLX1702 shell crack as found after jacket and insulation removal, August 29, 2016