

**WPR20CA112 – FAA-Provided Photographs**



**Figure 1 - Right Wingtip and Aileron**

**WPR20CA112 – FAA-Provided Photographs**




**Figure 2 - Interior of Right Wing**

**WPR20CA112 – FAA-Provided Photographs**



**Figure 3 - Right Wing Aileron Wrinkles and Cracks**

**WPR20CA112 – FAA-Provided Photographs**



**Figure 4 - Internal Rib Wrinkles**