


RECORD OF INTERVIEW

Date and time of Interview		Place of Interview	
12/22/2019		Mayaguez, PR	
Name/address of person interviewed Alberto Garcia Caraballo [REDACTED]		Name/address of person conducting Interview Dennis Ortiz FSDO-63 San Juan, PR	
Phone: <input type="checkbox"/> Home: <input type="checkbox"/> Work: <input checked="" type="checkbox"/> Mobile: [REDACTED]		Phone: <input type="checkbox"/> Home: <input checked="" type="checkbox"/> Work: [REDACTED] <input type="checkbox"/> Mobile:	
Reason for Interview Accident Investigation ASO6320002			
Other persons present			
Name: ASI Manuel Cepeda		Address: FSDO-63	Phone: 6500
Name:		Address:	Phone:
Did witness identify any additional witnesses that should be interviewed? If so, specify names and phone numbers. Jose Torres, Instructor			
Did witness identify any documents or other evidence that may be pertinent to this case? If so, where is it located?			

Does person interviewed have any specialized knowledge pertinent to the subject of the interview?

Remarks:

Interviewer Signature	FAA Office	File Number	Date
	FSDO-63	ASO6320002	12/22/2019

Mr. Alberto Garcia stated that while trying to take a picture of himself (Selfie) accidentally touched the fuel shutdown valve. The engine did shut down. Then he ditched on the water. The aircraft sank. He was able to escape with minor injuries that did not require hospitalization or medical help. Local boaters retrieved him.

Mr. Garcia stated that the aircraft's and pilot logbook sank with the aircraft. Mr. Garcia holds a current PR driver's license.

Use additional sheets as necessary