

# INSPECTION REPORT

Inspector's Name Le, Luong Van		Inspector's Signature			Inspector's ID No. [REDACTED]	Report No. 24	Date yy mm dd 2016 03 14						
Railroad/Company Name & Address BNSF RAILWAY COMPANY 1613 S JOHNSON STREET  AMARILLO TX 79101				R/C R	Division KANSAS	RR/Co. Representative (Receipt Acknowledged) Name MR. LARRY W. BRACKETT Title MANAGER OF SIGNALS Email [REDACTED] Signature _____							
From: City CIMARRON	Codes 0950	Destination City & County			Codes	From Latitude							
State KS	20	City				From Longitude							
County GRAY	C069	County				To Latitude							
Mile Post: From 0419.00 To 0371.00		Inspection Point				To Longitude							
Activity Code:	ABSO												
Units:	6												
Sub Units:	0												
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1				236						N	N	0	
Description - [** Comment to Railroad/Company **] CONDUCTED INITIAL INVESTIGATION OF THE ACCIDENT.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?			

Source Code C	File Number HQ-2016-1117	ID's of Accompanying Inspector(s)
------------------	-----------------------------	-----------------------------------