

INSPECTION REPORT

Inspector's Name SECORA, JEFF		Inspector's Signature			Inspector's ID No. [REDACTED]	Report No. 109	Date yy mm dd 2016 12 13						
Railroad/Company Name & Address UNION PACIFIC RR CO. Eagle Grove IA 50533				R/C R	Division TWICTI	RR/Co. Representative (Receipt Acknowledged) Name Dave Deurloo Title MTM Email Signature _____							
From: City SUPERIOR	Codes 8190	Destination City & County			Codes	From Latitude							
State IA	19	City EMMETSBURG			2760	From Longitude							
County DICKINSON	C059	County PALO ALTO			C147	To Latitude							
Mile Post: From 0078.40 To 0044.50		Inspection Point MAIN			To Longitude								
Activity Code:	MTH	MTW	RWP	DER	RMM	CWRP							
Units:	33	1	1	8	1	1							
Sub Units:	0	0	1	0	0	0							
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1										N	N	0	
Description - [** Comment to Railroad/Company **] NO DEFECTS NOTED, SNOW COVER. WE ALSO HAD A DISCUSSION ABOUT MARGINAL TIE CONDITIONS THAT EXIST BETWEEN SUPERIOR, IOWA AND EMMETSBURG. ESPECIALLY THE HILL AND CURVES WEST OF ESTHERVILLE AND BETWEEN EMMETSBURG AND ESTHERVILLE. FRA REPORT 67 DATED AUGUST 10TH, 2016 LISTED 10 AREAS OF DEFECTIVE TIE CONDITIONS. THIS CONDITION CAN ONLY GET WORSE GOING INTO THE NEXT YEAR. RAILROAD WILL NEED TO MONITOR THIS TIE CONDITION AND TAKE PROPER REMEDIAL ACTION IF NECESSARY.													
Violation Recommended				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:		Longitude:					
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?			

Source Code A	File Number R6-TRK-03-16	ID's of Accompanying Inspector(s)
-------------------------	------------------------------------	-----------------------------------

INSPECTION REPORT

Inspector's Name SECORA, JEFF		Inspector's Signature			Inspector's ID No. [REDACTED]	Report No. 110	Date yy mm dd 2016 12 14				
Railroad/Company Name & Address UNION PACIFIC RR CO. Eagle Grove IA 50533				R/C R	Division TWICTI	RR/Co. Representative (Receipt Acknowledged) Name Dave Deurloo Title MTM Email Signature _____					
From: City GOLDFIELD	Codes 3280	Destination City & County			Codes 2760	From Latitude					
State IA	19	City EMMETSBURG			2760	From Longitude					
County WRIGHT	C197	County PALO ALTO			C147	To Latitude					
Mile Post: From 0000.00 To 0048.90		Inspection Point MAIN			To Longitude						
Activity Code:	MTH	MTW	RWP	DER	RMM	CWRP	TOM	RXM			
Units:	48	1	1	9	1	1	13	1			
Sub Units:	0	0	3	0	0	0	0	0			

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	0032.30	SGL	M	213	0121	C2	30	3		N	N	1	MTW

Description
CENTER CRACKED OR BROKEN JOINT BAR (CWR). BOTH BARS CRACKED LH 115-90#

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code [][] Date(mm/dd/yyyy): [] Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	0032.40	SGL	M	213	0121	C3	30	3		N	N	1	MTW

Description
CENTER CRACKED OR BROKEN INSULATED JOINT BAR (CWR) 90# GAGE SIDE

Violation Recommended Yes No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code [][] Date(mm/dd/yyyy): [] Comments on back?

Source Code A	File Number R6-TRK-03-16	ID's of Accompanying Inspector(s)
------------------	-----------------------------	-----------------------------------