

INSPECTION REPORT

Inspector's Name Crowther, Frank W.		Inspector's Signature			Inspector's ID No. [REDACTED]	Report No. 123	Date yy mm dd 2016 09 28						
Railroad/Company Name & Address CSX TRANSPORTATION				R/C R	Division BALTIM		RR/Co. Representative (Receipt Acknowledged)						
Point of Rocks MD				RR/Co. Code CSX	Subdivision OLD MAIN LINE		Name Jeremy Helene	Title Roadmaster					
						Email [REDACTED]	Signature _____						
From: City ELLICOTT CITY	Codes 0530	Destination City & County			Codes	From Latitude							
State MD	24	City				From Longitude							
County HOWARD	C027	County				To Latitude							
Mile Post: From BAC0012.00 To BAC0013.00				Inspection Point WALK INSP. THROUGH TOWN			To Longitude						
Activity Code:	MTW	RWP	CWRP	MSB									
Units:	2	1	1	1									
Sub Units:	0	1	0	0									
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1										N	N	0	
Description - [** Comment to Railroad/Company **] NO DEFECTS NOTED FOR UNITS OBSERVED.													
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					Latitude:				Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional					Railroad Action Code <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			Date(mm/dd/yyyy): <input type="text"/>		Comments on back?			

Source Code A	File Number	ID's of Accompanying Inspector(s) [REDACTED]
------------------	-------------	---