

INSPECTION REPORT

Inspector's Name [REDACTED]		Inspector's Signature			Inspector's ID No [REDACTED]	Report No 58	Date yy mm dd 2016 06 28						
Railroad/Company Name & Address BNSF RAILWAY COMPANY 1100 Garfield Amarillo TX 79101				R/C R	Division KANSAS	RR/Co Representative (Receipt Acknowledged) Name [REDACTED] Title Signal Supervisor Email Signature							
From: City PANHANDLE		Codes 5200	Destination City & County			Codes	From Latitude						
State TX		48	City				From Longitude						
County CARSON		C065	County CARSON			C065	To Latitude						
Mile Post: From 0536.00		To 0520.00	Inspection Point			To Longitude							
Activity Code:	TCSS	TCSO											
Units:	14	5											
Sub Units:	0	0											
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ ***	Activity Code
1										N	N	0	
Description - [** Comment to Railroad/Company **] NO EXCEPTIONS NOTED TO UNITS INSPECTED													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?			

INSPECTION REPORT

Inspector's Name [REDACTED]		Inspector's Signature [REDACTED]				Inspector's ID No [REDACTED]	Report No 59	Date					
							yy 2016	mm 06	dd 29				
Railroad/Company Name & Address BNSF RAILWAY COMPANY 1100 Garfield Amarillo TX 79101				R/C R	Division KANSAS	RR/Co Representative (Receipt Acknowledged)							
				RR/Co Code BNSF	Subdivision PANHANDLE	Name [REDACTED]	Title Signal Supervisor						
						Email	Signature						
From: City PANHANDLE	Codes 5200	Destination City & County				Codes	From Latitude						
State TX	48	City					From Longitude						
County CARSON	C065	County CARSON				C065	To Latitude						
Mile Post: From 0536.00 To 0520.00		Inspection Point				To Longitude							
Activity Code:	TCSS	TCSO	TCSW										
Units:	14	8	1										
Sub Units:	0	0	0										
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ ***	Activity Code
1										N	N	0	
Description - [** Comment to Railroad/Company **] NO EXCEPTIONS NOTED TO UNITS INSPECTED													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?			

INSPECTION REPORT

Inspector's Name [REDACTED]			Inspector's Signature [REDACTED]				Inspector's ID No [REDACTED]		Report No 60		Date yy mm dd 2016 06 30		
Railroad/Company Name & Address BNSF RAILWAY COMPANY 1100 Garfield Amarillo TX 79101					R/C R	Division KANSAS		RR/Co Representative (Receipt Acknowledged) Name [REDACTED] Title Signal Supervisor Email Signature _____					
From: City PANHANDLE		Codes 5200		Destination City & County				Codes	From Latitude				
State TX		48		City					From Longitude				
County CARSON		C065		County CARSON				C065	To Latitude				
Mile Post: From 0536.00 To 0520.00			Inspection Point					To Longitude					
Activity Code:	TCSS	TCSO	TCSW										
Units:	28	8	2										
Sub Units:	0	0	0										
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ ***	Activity Code
1										N	N	0	
Description - [** Comment to Railroad/Company **] NO EXCEPTIONS NOTED TO UNITS INSPECTED													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					Latitude:			Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional					Railroad Action Code			Date(mm/dd/yyyy):		Comments on back?			

INSPECTION REPORT

Inspector's Name [REDACTED]		Inspector's Signature [REDACTED]			Inspector's ID No [REDACTED]	Report No 61	Date yy mm dd 2016 07 01						
Railroad/Company Name & Address BNSF RAILWAY COMPANY 1100 Garfield Amarillo TX 79101				R/C R RR/Co Code BNSF	Division KANSAS Subdivision PANHANDLE	RR/Co Representative (Receipt Acknowledged) Name [REDACTED] Title Signal Supervisor Email Signature _____							
From: City PANHANDLE	Codes 5200	Destination City & County			Codes	From Latitude							
State TX	48	City				From Longitude							
County CARSON	C065	County CARSON			C065	To Latitude							
Mile Post: From 0536.00 To 0520.00		Inspection Point				To Longitude							
Activity Code:	TCSS	TCSO											
Units:	8	2											
Sub Units:	0	0											
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ ***	Activity Code
1										N	N	0	
Description - [** Comment to Railroad/Company **] NO EXCEPTIONS NOTED TO UNITS INSPECTED													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		[REDACTED]		Comments on back?	

INSPECTION REPORT

Inspector's Name [REDACTED]		Inspector's Signature [REDACTED]			Inspector's ID No [REDACTED]	Report No 62	Date yy mm dd 2016 07 06						
Railroad/Company Name & Address BNSF RAILWAY COMPANY 1100 Garfield Amarillo TX 79102				R/C R	Division KANSAS	RR/Co Representative (Receipt Acknowledged) Name [REDACTED] Title Signal Supervisor Email Signature							
From: City PANHANDLE		Codes 5200	Destination City & County			Codes	From Latitude						
State TX		48	City				From Longitude						
County CARSON		C065	County CARSON			C065	To Latitude						
Mile Post: From 0520.00		To 0539.00	Inspection Point				To Longitude						
Activity Code:	TCSS	SMCP	RWP										
Units:	14	1	1										
Sub Units:	0	6	1										
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ ***	Activity Code
1										N	N	0	
Description - [** Comment to Railroad/Company **] NO EXCEPTIONS NOTED TO UNITS INSPECTED													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		[REDACTED]		Comments on back?	

INSPECTION REPORT

Inspector's Name [REDACTED]		Inspector's Signature [REDACTED]				Inspector's ID No [REDACTED]	Report No 63	Date					
							yy 2016	mm 07	dd 07				
Railroad/Company Name & Address BNSF RAILWAY COMPANY 1100 Garfield Amarillo TX 79102				R/C R	Division KANSAS	RR/Co Representative (Receipt Acknowledged)							
				RR/Co Code BNSF	Subdivision PANHANDLE	Name [REDACTED]	Title Signal Supervisor						
						Email	Signature						
From: City PANHANDLE	Codes 5200	Destination City & County			Codes	From Latitude							
State TX	48	City				From Longitude							
County CARSON	C065	County CARSON			C065	To Latitude							
Mile Post: From 0520.00 To 0533.00		Inspection Point HQ				To Longitude							
Activity Code:	SIGR												
Units:	1												
Sub Units:	315												
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ ***	Activity Code
1										N	N	0	
Description - [** Comment to Railroad/Company **] NO EXCEPTIONS NOTED TO RECORDS INSPECTED													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?			