

# INSPECTION REPORT

Inspector's Name Walker, Francis J.		Inspector's Signature			Inspector's ID No. 92855	Report No. 57	Date yy mm dd 2015 05 13						
Railroad/Company Name & Address AMTRAK (NATIONAL RAILROAD PASSENGER CORPORAT  PHILADELPHIA PA				R/C R	Division MIDATL	RR/Co. Representative (Receipt Acknowledged) Name PAT COLLINS Title TRACK SUPERVISOR Email Signature _____							
From: City PHILADELPHIA		Codes 6540	Destination City & County			Codes	From Latitude						
State PA		42	City				From Longitude						
County PHILADELPHIA		C101	County				To Latitude						
Mile Post: From 0081.60		To 0081.80	Inspection Point				To Longitude						
Activity Code:	MTW												
Units:	1												
Sub Units:	0												
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1										N	N	0	
Description - [** Comment to Railroad/Company **] I INSPECTED TRACK NO. 2 FROM MP 81.6 (POINT OF DERAILMENT) IN CURVE TO LUBRICATOR AT MP 81.8. I OBSERVED AND REVIEWED THE TAKING OF STRINGLINE NOTES REGARDING GAGE, SURFACE, AND ALIGNMENT AND NO EXCEPTIONS WERE NOTED FOR CLASS 3 TRACK.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?			

# INSPECTION REPORT

Inspector's Name Walker, Francis J.		Inspector's Signature			Inspector's ID No. 92855	Report No. 58	Date yy mm dd 2015 05 14						
Railroad/Company Name & Address AMTRAK (NATIONAL RAILROAD PASSENGER CORP.)  PHILADELPHIA PA				R/C R	Division MIDATL	RR/Co. Representative (Receipt Acknowledged) Name JOHN FIELD Title ENGINEER OF TRACK SPECIALIST Email fieldj@amtrak.com Signature _____							
From: City PHILADELPHIA		Codes 6540	Destination City & County			Codes	From Latitude						
State PA		42	City				From Longitude						
County PHILADELPHIA		C101	County				To Latitude						
Mile Post: From		To	Inspection Point RECORDS AT SYSTEM OFFICE				To Longitude						
Activity Code:	TREC												
Units:	3												
Sub Units:	40												
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1										N		0	
Description - [** Comment to Railroad/Company **] REVIEWED TRACK INSPECTION REPORTS FOR MP AN79.38 -AN82.31 FROM 1/1/15 THRU 5/12/15 FOR TRACK 2 IN AREA OF DERAILMENT AND REPORTS WERE REFLECTIVE OF ACTUAL CONDITIONS. REVIEWED GRMS DATA OF 5/20/14. ALSO REVIEWED AMTRAK GEOMETRY CAR STRIP CHART DATA OF 5/12/15. NO EXCEPTIONS WERE NOTED.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?			