



**HIGHWAY FACTORS GROUP CHAIRMAN'S  
FACTUAL REPORT**

**Highway Attachment – Terracon Core Sample Collection Report**

**Biloxi, Mississippi**

**HWY17MH010**

(3 pages)

# ASPHALT OBSERVATIONS REPORT

**Report Number:** E4171014.0001  
**Service Date:** 05/31/17  
**Report Date:** 06/05/17

# Terracon

285 Gulfwater Dr  
Biloxi, MS 39531-2629  
228-283-7050

---

## Client

National Transportation Safety Board (NTSB)  
Attn: Peter Kotowski  
490 L'Enfant Plaza East, S.W.  
Washington, DC 20594

## Project

Biloxi Train Track Crossing  
Main Street  
Biloxi, MS

Project Number: E4171014

---

A Terracon representative visited the above-referenced site to provide services by obtaining asphalt cores. Cores were obtained from 13 random locations chosen by the client. The client observed coring procedures and collected each core sample immediately after completion. Weather was cloudy with light rain most of the day.

## Services:

**Terracon Rep.:** Mark Saffle

**Reported To:** Steven Prouty, P.E.

**Contractor:**

**Report Distribution:**

(1) National Transportation Safety Board  
(NTSB), Peter Kotowski

(1) National Transportation Safety Board  
(NTSB), Steven Prouty, P.E.

**Reviewed By:**

rvwl: jww

  
Mark Saffle

Assistant Project Manager

The tests were performed in general accordance with applicable ASTM, AASHTO, or DOT test methods. This report is exclusively for the use of the client indicated above and shall not be reproduced except in full without the written consent of our company. Test results transmitted herein are only applicable to the actual samples tested at the location(s) referenced and are not necessarily indicative of the properties of other apparently similar or identical materials.

# ASPHALT OBSERVATIONS REPORT

Report E4171014.0001  
Service Date: 05/31/17  
Report Date: 06/05/17



285 Gulfwater Dr  
Biloxi, MS 39531-2629  
228-283-7050

## Client

National Transportation Safety Board (NTSB)  
Attn: Peter Kotowski  
490 L'Enfant Plaza East, S.W.  
Washington, DC 20594

## Project

Biloxi Train Track Crossing  
Main Street  
Biloxi, MS

Project Number: E4171014



Photo No. 1 View Northeast.



Photo No. 2 View Southwest.



Photo No. 3 View Southwest.



Photo No. 4 View Northwest.

## Services:

Terracon Rep.: Mark Saffle

Reported To: Steven Prouty, P.E.

Contractor:

Report Distribution:

(1) National Transportation Safety Board  
(NTSB), Peter Kotowski

(1) National Transportation Safety Board  
(NTSB), Steven Prouty, P.E.

Reviewed By:

rvwl: jww

  
Mark Saffle

Assistant Project Manager

The tests were performed in general accordance with applicable ASTM, AASHTO, or DOT test methods. This report is exclusively for the use of the client indicated above and shall not be reproduced except in full without the written consent of our company. Test results transmitted herein are only applicable to the actual samples tested at the location(s) referenced and are not necessarily indicative of the properties of other apparently similar or identical materials.