



HIGHWAY FACTORS GROUP

Photographs

Oakland, Iowa

HWY18MH0003

(7 photographs)



Highway Photograph 1 – Crash Location – Facing Northwest



Highway Photograph 2 – Roadway at Crash Location – Facing South



Highway Photograph 3 – School Bus at Final Rest Following the Collision and Post-Crash Fire – Facing South (source: Pottawattamie County Sheriff's Office)



Depression from Right
Rear Inner Tire

Depression from Right
Rear Outer Tire


Highway Photograph 4 – Right Rear Tire Depressions Near the Bottom of Ditch Foreslope



Highway Photograph 5 – Triangular Depression in Soil of Ditch Backslope – Facing Southeast



Highway Photograph 6 – Right Rear Corner of School Bus at Final Rest Against the Ditch Backslope Following the Collision and Post-Crash Fire (source: Pottawattamie County Sheriff's Office)



**Triangular Depression
with Unburned
Vegetation**

Streak of Soot

Highway Photograph 7 – Area of Suspected Soot Deposits on Ditch Backslope