



**HIGHWAY FACTORS AND RAILROAD GRADE CROSSING
GROUP CHAIRMAN'S FACTUAL REPORT**

**Highway and Rail Crossing Attachment – Buckingham Branch Railroad –
Richmond & Alleghany Division Operating Bulletin 137**

Crozet, Virginia

HWY18MH005

(3 pages)

**Buckingham Branch Railroad
Richmond & Alleghany Division
Current Operating Bulletin 137
Effective at 15:45 January 30, 2018**

Timetable Number: 2

General Order(s) in Effect: 11

Piedmont Subdivision

Void	Item	Form	Limits	Speed (MPH)	From - Until	Foreman	Flag	F.Int. - DATE - Condition
	1	C	MP 101 - MP 108					Poor walking conditions both sides of tracks ties distributed 09/20/17
	2	A	MP 106.6 - MP 106.8	10F			YES	06/02/17
	3	C	MP 112 - MP 114					CSX bulletins issued for BB local trains will have the following train IDs: (Z710=Z710) (Z631=Z631) (Z628=Z373) (Z629=Z609) (Z626=Z371) (Z799=Z807). 11/28/17
	4	A	MP 128.2 - MP 128.3	10F			YES	01/23/18
	5	C	MP 145.14					Be on the lookout for increased traffic due to logging operation. 12/20/17
	6	C	MP 152.6					Be on the lookout for increased truck traffic due to logging operation. 08/10/17
	7	C	MP 157.16					Be on the lookout for increased traffic due to logging operation. 01/03/18

Orange Subdivision (CTC)

	8							No Restrictions
--	---	--	--	--	--	--	--	-----------------

North Mountain Subdivision (CTC)

Void	Item	Form	Limits	Speed (MPH)	From - Until	Foreman	Flag	F.Int. - DATE - Condition
	9	C	MP 180.1 - MP 183.1					Quiet Zone: The locomotive horn must not be sounded between MP 180.1 and MP 183.1 except when emergencies require sounding of the horn. 11/30/17
	10	C	MP 193.89					There is now a temporary(6 months or more) private crossing at MP 193.89. DOT# 967955B 10/04/16
	11	C	MP 194.6					Track equipment stored in Crozet spur track 08/10/17
	12	A	MP 204.8 - MP 205	25F 30P			YES	03/24/17
	13	A	MP 207.7 - MP 207.9	25F 30P			YES	07/10/17
	14	C	MP 208.1					Walkway on Northside of Track OOS 02/17/16
	15	C	MP 219.7					Equipment stored at the end of Staunton Industry Track. 12/21/17
	16	C	MP 222.1					At Factory, track OOS inside the gate. 10/04/17
	17	C	MP 234.2 - MP 240.6					Poor walking conditions on both sides of main track due to ties. 10/11/16
	18	A	MP 241.8 - MP 242	50P			NO	09/21/17
	19	A	MP 255.5 - MP 256.3	55P			NO	09/22/17
	20	C	MP 267					Crane Spur track new portable derail installed 01/30/18

END OF Current Operating Bulletin 137 January 30, 2018

TOTAL OF 20 ITEMS