



HUMAN PERFORMANCE FACTORS

Attachment 1- Accident Vehicle

GPS Download

Chattanooga, TN

HWY15MH009

(7 pages)

Latitude	Longitude	Date-Time Stamp of Data	Time Between Data Reporting (hh:mm:ss)	Distance Between Position in Miles	Distance Between Positions in Feet (where d<1 mile)	Log Code	Comments
37.1444015503	-84.1151199341	6/21/2015 01:23:57 AM				BPS	Position indicates vehicle at a facility
37.1444015503	-84.1150970459	6/21/2015 05:23:57 AM	4:00:00	0.00	6.7	BPS	Position indicates vehicle at a facility
37.1444168091	-84.1151504517	6/21/2015 09:23:57 AM	4:00:00	0.00	16.5	BPS	Position indicates vehicle at a facility
37.1443672180	-84.1151199341	6/21/2015 01:23:58 PM	4:00:01	0.00	20.1	BPS	Position indicates vehicle at a facility
37.1446838379	-84.1151962280	6/21/2015 05:23:57 PM	4:00:00	0.02	117.6	BPS	Position indicates vehicle at a facility
37.1433334351	-84.1149978638	6/21/2015 06:01:57 PM	0:38:00	0.09	496.0	4PO	Position indicates vehicle at a facility
37.1433334351	-84.1149978638	6/21/2015 08:14:27 PM	2:12:30	0.00	0.0	4PO	Position indicates vehicle at a facility
37.1444015503	-84.1151809692	6/21/2015 11:23:29 PM	3:09:01	0.07	393.3	BPS	Position indicates vehicle at a facility
37.1444664001	-84.1151809692	6/22/2015 01:02:45 AM	1:39:17	0.00	23.7	TPR	Position indicates vehicle at a facility
37.1444320679	-84.1151809692	6/22/2015 03:23:27 AM	2:20:42	0.00	12.5	BPS	Position indicates vehicle at a facility
37.1444015503	-84.1151962280	6/22/2015 06:08:02 AM	2:44:35	0.00	12.0	SSR	Position indicates vehicle at a facility
37.1444511414	-84.1151962280	6/22/2015 07:23:27 AM	1:15:25	0.00	18.1	BPS	Position indicates vehicle at a facility
37.1444664001	-84.1151351929	6/22/2015 11:23:27 AM	4:00:00	0.00	18.6	BPS	Position indicates vehicle at a facility
37.1490173340	-84.1168670654	6/22/2015 12:26:33 PM	1:03:06	0.33	1734.9	SSR	Position indicates on Route 80 (London Road) less than 800 feet from starting location
36.9938011169	-85.8793334961	6/22/2015 02:19:33 PM	1:53:00	97.75	NA	SSR	On highway
36.9938011169	-85.8793334961	6/22/2015 02:20:42 PM	0:01:10	0.00	0.3	SSR	On highway
36.9938163757	-85.8793640137	6/22/2015 02:26:33 PM	0:05:50	0.00	10.5	SSR	On highway
36.9938163757	-85.8793640137	6/22/2015 02:27:43 PM	0:01:10	0.00	0.0	SSR	On highway
36.9938316345	-85.8793182373	6/22/2015 02:31:32 PM	0:03:50	0.00	14.5	SSR	On highway
36.9929847717	-85.8817977905	6/22/2015 02:35:33 PM	0:04:01	0.15	785.8	SSR	On highway

37.1791992188	-85.9079818726	6/22/2015 03:13:03 PM	0:37:30	12.95	NA	SSR	Position indicates vehicle at a facility
37.1791496277	-85.9079818726	6/22/2015 03:18:02 PM	0:04:59	0.00	18.1	SSR	Position indicates vehicle at a facility
37.1791648865	-85.9080810547	6/22/2015 03:23:33 PM	0:05:31	0.01	29.4	SSR	Position indicates vehicle at a facility
37.1791152954	-85.9080200195	6/22/2015 03:24:07 PM	0:00:35	0.00	25.3	BPS	Position indicates vehicle at a facility
37.1757507324	-85.9084167480	6/22/2015 03:48:34 PM	0:24:27	0.23	1232.8	SSR	Position indicates on highway along Route 31W, just south of position above
37.1591491699	-85.9162368774	6/22/2015 04:01:38 PM	0:13:04	1.23	NA	SSR	Position indicates vehicle at a facility
37.1591835022	-85.9162521362	6/22/2015 06:35:32 PM	2:33:55	0.00	13.3	SSR	Position indicates vehicle at a facility
37.1591835022	-85.9162521362	6/22/2015 06:40:28 PM	0:04:56	0.00	0.3	SSR	Position indicates vehicle at a facility
37.1591835022	-85.9162673950	6/22/2015 07:23:29 PM	0:43:01	0.00	4.4	BPS	Position indicates vehicle at a facility
37.1592178345	-85.9162521362	6/22/2015 11:23:28 PM	3:59:59	0.00	13.3	BPS	Position indicates vehicle at a facility
37.1592330933	-85.9162368774	6/23/2015 01:02:28 AM	1:39:00	0.00	7.1	TPR	Position indicates vehicle at a facility
37.1590652466	-85.9166488647	6/23/2015 02:51:33 AM	1:49:05	0.03	134.5	SSR	Position indicates vehicle at a facility
37.1589508057	-85.9166336060	6/23/2015 02:57:03 AM	0:05:30	0.01	42.0	SSR	Position indicates vehicle at a facility
37.1589317322	-85.9166336060	6/23/2015 03:23:29 AM	0:26:26	0.00	7.0	BPS	Position indicates vehicle at a facility
37.1623840332	-85.9170303345	6/23/2015 04:44:03 AM	1:20:34	0.24	1264.7	SSR	On highway
37.1443328857	-84.1157989502	6/23/2015 07:01:13 AM	2:17:10	99.20	NA	SSR	Position indicates vehicle at a facility
37.1433334351	-84.1149978638	6/23/2015 07:01:48 AM	0:00:35	0.08	432.7	4PO	Position indicates vehicle at a facility
37.1443481445	-84.1158142090	6/23/2015 07:03:03 AM	0:01:15	0.08	439.8	SSR	Position indicates vehicle at a facility
37.1451683044	-84.1148300171	6/23/2015 08:48:34 AM	1:45:31	0.08	414.0	SSR	Position indicates vehicle at a facility
37.1073150635	-84.1006317139	6/23/2015 09:01:33 AM	0:12:59	2.73	NA	SSR	Position indicates vehicle at a facility
37.1073150635	-84.1006698608	6/23/2015 10:09:28 AM	1:07:55	0.00	11.1	BPS	Position indicates vehicle at a facility
37.1066665649	-84.0999984741	6/23/2015 11:32:28 AM	1:23:01	0.06	306.8	4PO	Position indicates vehicle at a facility
37.1073341370	-84.1006164551	6/23/2015 11:38:32 AM	0:06:03	0.06	302.7	SSR	Position indicates vehicle at a facility

37.1073150635	-84.1006164551	6/23/2015 11:44:33 AM	0:06:01	0.00	7.0	SSR	Position indicates vehicle at a facility
37.1100997925	-84.0986862183	6/23/2015 02:11:04 PM	2:26:30	0.22	1160.8	SSR	On highway
37.1439018250	-84.1153182983	6/23/2015 02:24:33 PM	0:13:29	2.51	NA	SSR	Position indicates vehicle at a facility
37.1437683105	-84.1154174805	6/23/2015 02:26:33 PM	0:02:01	0.01	56.6	SSR	Position indicates vehicle at a facility
37.1439666748	-84.1155700684	6/23/2015 02:32:02 PM	0:05:29	0.02	84.9	SSR	Position indicates vehicle at a facility
37.1456489563	-84.1148529053	6/23/2015 02:40:32 PM	0:08:30	0.12	648.2	SSR	Position indicates vehicle at a facility - Possibly start of departure
37.1465682983	-84.1148986816	6/23/2015 02:46:03 PM	0:05:30	0.06	335.7	SSR	Movement toward departing facility
37.1465492249	-84.1125640869	6/23/2015 03:01:33 PM	0:15:30	0.13	678.9	SSR	On highway - ramp to I-75
37.1082496643	-84.1007308960	6/23/2015 03:13:27 PM	0:11:54	2.73	NA	SSR	Position indicates vehicle at a facility
37.1084823608	-84.0998992920	6/23/2015 03:14:38 PM	0:01:11	0.05	256.4	SSR	Position indicates vehicle at a facility
37.1084175110	-84.0998992920	6/23/2015 03:19:02 PM	0:04:24	0.00	23.7	SSR	Position indicates vehicle at a facility
37.1074333191	-84.1008300781	6/23/2015 03:21:34 PM	0:02:32	0.09	449.7	SSR	Position indicates vehicle at a facility
37.1074333191	-84.1006469727	6/23/2015 03:27:03 PM	0:05:30	0.01	53.3	SSR	Position indicates vehicle at a facility
37.1074485779	-84.1006011963	6/23/2015 03:35:02 PM	0:07:59	0.00	14.4	SSR	Position indicates vehicle at a facility
37.1083335876	-84.0999984741	6/23/2015 05:05:28 PM	1:30:26	0.07	367.4	4PO	Position indicates vehicle at a facility
37.1103668213	-84.0985641479	6/23/2015 05:08:33 PM	0:03:05	0.16	851.1	SSR	On highway (outside Peterbilt facility)
37.1116676331	-84.0983352661	6/23/2015 05:11:57 PM	0:03:24	0.09	479.2	4PO	On highway
36.9750175476	-84.1061859131	6/23/2015 06:52:33 PM	1:40:36	9.45	NA	SSR	Position indicates near entrance of facility
36.9745178223	-84.1064987183	6/23/2015 06:58:03 PM	0:05:30	0.04	203.8	SSR	Position indicates vehicle at a facility
36.9751167297	-84.1061325073	6/23/2015 07:06:33 PM	0:08:30	0.05	243.2	SSR	Position indicates vehicle at a facility
36.9173164368	-84.1343994141	6/23/2015 07:20:33 PM	0:14:01	4.29	NA	SSR	On highway
36.9178504944	-84.1321182251	6/23/2015 07:28:29 PM	0:07:55	0.13	693.3	SSR	On highway
36.5133323669	-84.1965637207	6/23/2015 07:58:03 PM	0:29:34	28.18	NA	DTX	On highway (I-75)

36.1706848145	-84.0854797363	6/23/2015 08:26:02 PM	0:27:59	24.47	NA	BPS	On highway (I-75)
36.1109504700	-84.0201492310	6/23/2015 08:35:02 PM	0:09:00	5.51	NA	SSR	Position indicates vehicle at a facility
36.1084175110	-84.0225982666	6/23/2015 08:59:02 PM	0:24:00	0.22	1172.6	SSR	On highway
34.9315185547	-85.1540985107	6/23/2015 10:43:03 PM	1:44:00	103.25	NA	DTX	On highway
34.5639495850	-84.9457168579	6/23/2015 11:17:03 PM	0:34:00	28.02	NA	SSR	Highway rest area, southbound I-75
34.5622329712	-84.9444351196	6/23/2015 11:22:39 PM	0:05:36	0.14	735.2	SSR	Highway rest area, southbound I-75
33.7835159302	-84.4955978394	6/24/2015 12:22:28 AM	0:59:49	59.61	NA	BPS	On highway
33.3927345276	-84.1474151611	6/24/2015 01:02:06 AM	0:39:38	33.62	NA	TPR	On highway (I-75)
33.2079658508	-84.0654830933	6/24/2015 01:21:58 AM	0:19:52	13.61	NA	SSR	Position indicates vehicle at a facility
33.2064514160	-84.0628967285	6/24/2015 01:50:32 AM	0:28:34	0.18	963.6	SSR	Position indicates vehicle at/adjacent a facility
33.2080001831	-84.0643005371	6/24/2015 01:58:33 AM	0:08:01	0.13	709.1	SSR	Position indicates vehicle at a facility
33.2065849304	-84.0628356934	6/24/2015 02:32:33 AM	0:34:00	0.13	683.0	SSR	On highway
31.6342334747	-83.5851516724	6/24/2015 04:21:33 AM	1:49:00	112.15	NA	SSR	Highway rest area #9, southbound I-75
31.6342658997	-83.5851516724	6/24/2015 04:24:02 AM	0:02:29	0.00	11.8	BPS	Highway rest area #9, southbound I-75
31.6331157684	-83.5835494995	6/24/2015 05:03:33 AM	0:39:30	0.12	650.9	SSR	Highway rest area #9, southbound I-75
30.7530670166	-83.2716140747	6/24/2015 06:07:33 AM	1:04:01	63.54	NA	SSR	Position indicates vehicle at a facility
30.7539672852	-83.2723693848	6/24/2015 06:31:33 AM	0:24:00	0.08	404.9	SSR	On highway outside facility
30.6124668121	-83.1482162476	6/24/2015 06:45:33 AM	0:14:00	12.25	NA	DTX	Highway rest area
30.6124839783	-83.1482467651	6/24/2015 06:47:58 AM	0:02:24	0.00	11.4	SSR	Highway rest area

30.6126670837	-83.1444015503	6/24/2015 07:01:37 AM	0:13:39	0.23	1209.1	SSR	On highway - departing rest area
29.9793491364	-82.5794525146	6/24/2015 07:56:33 AM	0:54:56	55.23	NA	SSR	Highway rest area
29.9787826538	-82.5791473389	6/24/2015 08:09:32 AM	0:13:00	0.04	228.1	SSR	Highway rest area
29.7659168243	-82.5051498413	6/24/2015 08:22:33 AM	0:13:00	15.36	NA	BPS	On highway (I-75)
28.8494167328	-82.0823974609	6/24/2015 09:28:04 AM	1:05:31	68.25	NA	SSR	On highway - STOP
28.8493824005	-82.0823822021	6/24/2015 12:22:28 PM	2:54:24	0.00	13.4	BPS	On highway - STOP
28.8483333588	-82.0816650391	6/24/2015 12:43:57 PM	0:21:29	0.08	446.1	4PO	On highway - STOP
28.8483333588	-82.0816650391	6/24/2015 01:22:28 PM	0:38:31	0.00	0.0	4PO	On highway - STOP
28.8489170074	-82.0816802979	6/24/2015 01:37:03 PM	0:14:34	0.04	213.0	SSR	On highway - STOP
28.8394832611	-82.0453491211	6/24/2015 01:46:33 PM	0:09:30	2.29	NA	SSR	On highway - Possible Stop
28.8398494720	-82.0455703735	6/24/2015 02:41:33 PM	0:55:00	0.03	151.2	SSR	On highway - Possible Stop (U-turn)
28.2280158997	-81.6481704712	6/24/2015 04:28:03 PM	1:46:30	48.67	NA	SSR	Position indicates vehicle at a facility
28.2274169922	-81.6469650269	6/24/2015 04:29:13 PM	0:01:10	0.08	444.8	SSR	On highway - departing facility
28.2075157166	-81.6399841309	6/24/2015 04:30:58 PM	0:01:45	1.44	NA	BPS	On highway - US 27
28.1192340851	-81.6393966675	6/24/2015 04:50:03 PM	0:19:04	6.10	NA	SSR	Position indicates vehicle at a facility
28.1191005707	-81.6392135620	6/24/2015 08:30:58 PM	3:40:55	0.01	76.4	BPS	Position indicates vehicle at a facility
28.1191005707	-81.6392135620	6/25/2015 12:30:58 AM	4:00:00	0.00	0.0	BPS	Position indicates vehicle at a facility
28.1190662384	-81.6391830444	6/25/2015 01:01:35 AM	0:30:37	0.00	15.9	TPR	Position indicates vehicle at a facility
28.1190834045	-81.6391830444	6/25/2015 04:30:58 AM	3:29:22	0.00	6.3	BPS	Position indicates vehicle at a facility
28.1209831238	-81.6397018433	6/25/2015 05:16:33 AM	0:45:35	0.14	712.9	SSR	On highway
28.0811328888	-81.6145858765	6/25/2015 05:32:04 AM	0:15:31	3.15	NA	SSR	Position indicates vehicle at a facility

28.0811328888	-81.6157531738	6/25/2015 07:45:58 AM	2:13:54	0.07	375.7	SSR	Position indicates vehicle at a facility - roadway departing facility
28.0944671631	-81.9566497803	6/25/2015 08:30:58 AM	0:45:00	20.80	NA	BPS	On highway
28.2161502838	-82.3680648804	6/25/2015 09:12:02 AM	0:41:04	26.44	NA	SSR	Highway rest area
28.2161159515	-82.3680191040	6/25/2015 09:21:32 AM	0:09:30	0.00	19.3	SSR	Highway rest area
30.4516830444	-82.9354324341	6/25/2015 12:02:32 PM	2:41:00	158.20	NA	SSR	Position indicates vehicle at a facility
30.4526329041	-82.9340362549	6/25/2015 12:27:03 PM	0:24:30	0.11	559.3	SSR	Position indicates vehicle at a facility
30.4820499420	-82.9915008545	6/25/2015 12:30:58 PM	0:03:55	3.98	NA	BPS	On highway (I-75)
30.6638660431	-83.2076492310	6/25/2015 12:47:03 PM	0:16:04	17.98	NA	DTX	Highway rest area
30.6638336182	-83.2076187134	6/25/2015 12:51:33 PM	0:04:30	0.00	15.2	SSR	Highway rest area
30.6653995514	-83.2094345093	6/25/2015 01:10:02 PM	0:18:30	0.15	806.9	SSR	Highway rest area - departing ramp
30.7529163361	-83.2714004517	6/25/2015 01:23:32 PM	0:13:30	7.08	NA	SSR	Position indicates vehicle at a facility
30.7525825500	-83.2702865601	6/25/2015 01:26:58 PM	0:03:26	0.07	369.8	SSR	Position indicates vehicle at a facility
30.7530002594	-83.2699356079	6/25/2015 01:33:03 PM	0:06:05	0.04	188.0	SSR	Position indicates vehicle at a facility
30.7534160614	-83.2712631226	6/25/2015 01:41:04 PM	0:08:01	0.08	443.0	SSR	Position indicates vehicle at a facility
33.5842666626	-84.3739166260	6/25/2015 04:33:03 PM	2:51:59	205.95	NA	BPS	On highway (I-75)
34.4077491760	-84.9183349609	6/25/2015 06:21:32 PM	1:48:29	64.88	NA	SSR	Highway rest area
34.4078674316	-84.9181976318	6/25/2015 06:23:33 PM	0:02:01	0.01	59.7	SSR	Highway rest area
35.0876007080	-85.0646362305	6/25/2015 07:15:29 PM	0:51:56	47.70	NA	SSR	Crash site
35.0875511169	-85.0645675659	6/25/2015 08:30:57 PM	1:15:28	0.01	27.3	BPS	Crash site