## MP 608 – Marshall, Michigan Incident NTSB/PHMSA Information Request No. 68

68 Reference: Email request by Matt Nicholson on October 1, 2010

## Preamble:

## Request:

Provide a table of all inline inspections performed on the 6b line (The HCA Mgmt Guide has a table that does not look complete). Include Magnetic Flux, Ultrasonic and Caliper tool runs. Include the Tool type, vendor, Mile posts or stations inspected, date of the inspection, date of first report, any re-issues and date of final report for each run.

Required by: October 14th, 2010

**Response:** The HCA Management Plan only contains re-assessments of a line; not a complete historical listing.

The requested information is contained in the table below.

ENBRIDGE LINE 6B IN-LINE INSPECTION INFORMATION											
Year of Inspection	Tool Type	Tool Vendor	Area Inspected	Inspection Date	Date of First Report	No. of Reissues	Date of Final Report				
2010	USCD - Crack	GE	Griffith (MP 465.58) to Stockbridge (MP 650.58)	July 2010	Report not received	-	-				
2010	Geometry	GE	Stockbridge (MP 650.58 ) to Sarnia (MP 758.2)	May 2010	Report not received	-	-				
2010	Geometry	GE	Entire Line	April to May 2010	Report not received	-	-				
2009	Vectra – Secondary damage in dent	y lent BJ	Entire Line	October 2009	January 2010	1	March 2010				
	Analysis of above data for Corrosion				March 2010	0	March 2010				
2009	USWM - Corrosion	GE	Entire Line	June 2009	December 2009	1	June 2010				
2009	XGP – Geometry	Rosen	Entire Line	May 2009	July 2009	2	October 2010				
2007	Magnascan - Corrosion	GE	Entire Line	July to October 2007	November 2008	3	May 2009				
2007	Ctool - Geometry	Donsa (Axiom)	Entire Line	May 2007	July 2007	0	July 2007				
2005	USCD - Crack	GE	Entire Line	October to December 2005	March 2006	0	March 2006				
2005	Ctool - Geometry	Donsa (Axiom)	Entire Line	July to August 2005	August 2005	0	August 2005				
2004	USWM - Corrosion	PII	Entire Line	February 2004 (USWM)	June 2004	1	September 2008				
2004	Geopig - Geometry	BJ	Entire Line	January 2004	August 2004	0	August 2004				

ENBRIDGE LINE 6B IN-LINE INSPECTION INFORMATION											
Year of Inspection	Tool Type	Tool Vendor	Area Inspected	Inspection Date	Date of First Report	No. of Reissues	Date of Final Report				
		Donsa					March				
2004	Ctool - Geometry	(Axiom)	Entire Line	January 2004	March 2004	0	2004				
2000	USWM - Corrosion	PII	Mendon (MP 576.9) to Sarnia (MP 758.2)	November 2000	February 2001	0	February 2001				
2000	CONOSION	ГП	10 Sattila (IVIF 750.2)			0	2001				
2000	Caliper	TDW	Entire Line	October 2000	Report not dated	0					
	USWM -		Griffith (MP 465.58) to Mendon (MP								
1999	Corrosion	PII	576.9)	October 1999	May 2000	1	July 2003				
1999	Geometry	Enduro	Entire Line	September 1999	Report not dated	0					
1994	MFL - Corrosion	British Gas (PII)	Entire Line	December 1994	Report not dated	0					
1993	MagneScan HR	Pipetronix	Entire Line	November to December 1993	Report not dated	0					
1988	EML - Corrosion	IPEL	Entire Line	July to November 1988	December 1988	0	December 1988				
1979	Corrosion	Vetco Pipeline Services	Entire Line	August 1979	November 1979	0	November 1979				
1979	Geometry	TDW	New construction (7 loops)	August to September 1979	October 1979	0	October 1979				
1978	Geometry	TDW	Entire Line	July 1978	September 1978	0	September 1978				
1976	Geometry	TDW	New construction (loops C1-C5)	July to September 1976	January 1977	0	January 1977				