

NATIONAL TRANSPORTATION SAFETY BOARD
Vehicle Recorder Division
Washington, DC 20594

July 19, 2018

Image Recordings

Specialist's Factual Report
By Jane Foster

1. EVENT

Location:	Biloxi, Mississippi
Vehicle #1:	2016 Vanhool Motor coach
Operator #1:	Echo Transportation
Vehicle #2:	Locomotive
Operator #2:	CSX
Date:	March 7, 2017
NTSB Number:	HWY17MH010

2. GROUP

In agreement with the Investigator-In-Charge, a video group did not convene and a summary report was prepared.

3. SUMMARY

For a summary of the crash, refer to the *Crash Summary Report* in the docket for this investigation.

4. DETAILS OF INVESTIGATION

The National Transportation Safety Board (NTSB) Vehicle Recorder Division received the following image recordings:

Recorder Manufacturer/Model:	Cell Phone Video File
Recorder Serial Number:	n/a
Recorder Manufacturer/Model:	Security Video File
Recorder Serial Number:	n/a
Recorder Manufacturer/Model:	Biloxi Police Dashboard Camera Files
Recorder Serial Number:	n/a
Recorder Manufacturer/Model:	Biloxi Police Body Camera Files
Recorder Serial Number:	n/a

4.1. Cell Phone Video File Description

The cell phone video file was retrieved from a witness to the March 7, 2017 crash.

4.1.1. Cell Phone Video File Summary of Recording Contents

The video shows the impact of the train and the bus, and the bus being dragged along the tracks by the moving train.

4.2. Security Video File Description

The security video camera system was a motion detecting system and only recorded when the system detected motion. The Security Video Files contained nine different camera angles. Only one of the camera angles was focused nearby the event and did not capture the crash event.

4.2.1. Security Video File Summary of Recording Contents

The one video that was focused nearby the crash did not capture the crash event but showed a limited view of the emergency response.

4.3. Biloxi Police Dashboard Camera Files Description

The Biloxi Police dashboard camera files were a series of forward facing videos from the point of view of the windshield of different police vehicles.

4.3.1. Biloxi Police Dashboard Camera Files Summary of Recording Contents

The Biloxi Police dashboard cameras did not capture the crash event but showed a limited view of the emergency response.

4.4. Biloxi Police Body Camera Files Description

The Biloxi Police body camera files were a series of forward facing videos from the point of view of different police officers.

4.4.1. Biloxi Police Body Camera Files Summary of Recording Contents

The Biloxi Police body cameras did not capture the crash event but showed a limited view of the emergency response.