

Filipino engineer, from 0400 to 0800 watch.

CHRISTOPHER SUMAYLO-He was in the forward generator, then 0630 he heard some a “whooom” and shaking, then two minutes later, the blackout, then some explosion, he found some engineer to help him. He saw the stabilizer was closed, found somebody to help. He relieved Mr. Manaman. There were no problems reported when watch was relieved.

He checked generators, temperatures, checked water in the tanks, oil spill in engine. Every 30 minutes he makes a round and checks the generators. Round includes forward stabilizer and other stuff but not the boiler room. From 0800 to 1000 was to work two hours of overtime on the evaporators-he was doing this two hours of overtime every day. Never works on the boilers for his overtime work. Never been told of problems with the boilers.

He felt a rush of air.