



**Photo 1 – Aerial View of Collision Location (Photo Courtesy of USAF)**



**Photo 2 – Cessna Aft Fuselage and Empennage at Collision Site**



**Photo 3 – Cessna Aft Fuselage and Empennage Post Recovery**



**Photo 4 – Cessna Tail Empennage**



**Photo 5 – Cessna Left Wing**



**Photo 6 – Cessna Right Wing**



**Photo 7 – Paint Scorching on Upper Side of Right Wing**



**Photo 8 – Recovered Portions of Cessna Cabin**





**Photo 9 – F-16 Engine Augmenter (Recovered from Collision Site)**



**Photo 10 – Wreckage Path at F-16 Impact Site**



**Photo 11 – F-16 Main Wreckage**



**Photo 12 – F-16 Main Wreckage**