

Photo 1 – Wreckage from left.



Photo 2 – Wreckage from front



Photo 3 – View from left front pilot seat (note position of flight control yoke)




Photo 4 – Damage to trees in immediate vicinity of wreckage



Photo 5 – View of circuit breaker and switch panel.