



Photo 1 –View of Airplane at rest (Courtesy of FAA)



Photo 2 – View of Fuselage Damage (Courtesy of FAA)



Photo 3 – Close up view of fuselage rib damage (Courtesy of FAA)