



Photo 1 –View of airplane after it came to rest inverted and was recovered (Courtesy of FAA)



Photo 2 – View of Rudder Damage (Courtesy of FAA)



Photo 3 – View of Right Wing Strut Damage (Courtesy of FAA)