



Photo 1 –View of Airplane at rest (Courtesy of FAA)



Photo 2 – View of Left Wing Damage (Courtesy of FAA)



Photo 3 – View of engine mount damage (Courtesy of FAA)



Photo 4 – View of wrinkled right wing (Courtesy of FAA)