



Investigative Photographs

Peter Wentz
Air Safety Investigator
Eastern Region Aviation

ERA20CA148

April 27, 2020




Photograph 1¹ – Accident airplane – left side view.

¹ Photograph provided by Central Air Southwest.



Photograph 2² – Damaged former (station 134).



Photograph 3³ – Station located diagram.

² Photograph provided by Central Air Southwest.

³ Photograph provided by Central Air Southwest.



Photograph 4⁴ – Lower fuselage skin damage between stations 134 and 165.



Photograph 4⁵ – Lower fuselage skin damage to station 180.

⁴ Photograph provided by Central Air Southwest.

⁵ Photograph provided by Central Air Southwest.