




**Photo 1 – Main wreckage**



**Photo 2 – Instrument panel**



**Photo 3 – Cabin Seats**



**Photo 4 – Rear of engine, loose fuel line in red circle.**



**Photo 5 – Firewall, burn pattern**