

Photo Array for ERA20CA065

Photographs provided by the Federal Aviation Administration



Photograph 1 - Accident airplane as seen from the front left side.



Photograph 2 - Accident airplane as seen from the right side.

Photo Array for ERA20CA065

Photographs provided by the Federal Aviation Administration



Photograph 3 - Accident airplane as seen from the left side.



Photograph 4 - Accident airplane engine cowling and nose wheel.

Photo Array for ERA20CA065

Photographs provided by the Federal Aviation Administration



Photograph 5 - Accident airplane's right wing.



Photograph 6 - Accident airplane's instrument panel.