

# INSPECTION REPORT

Inspector's Name BECK, THOMAS G		Inspector's Signature 			Inspector's ID No. 	Report No. 2	Date yy mm dd 2017 01 05						
Railroad/Company Name & Address LONG ISLAND RAIL ROAD 93-29 183rd street  Hollis NY 11423				R/C R	Division SYSTEM	RR/Co. Representative (Receipt Acknowledged) Name FRANK PRIOLO Title TRACK SUPERVISOR Email Signature _____							
From: City NEW YORK -QUEENS	Codes 4170	Destination City & County			Codes	From Latitude							
State NY	36	City			From Longitude								
County QUEENS	C081	County			To Latitude								
Mile Post: From To		Inspection Point HILLSIDE OFFICE FACILITY			To Longitude								
Activity Code:	RWP	TREC											
Units:	1	1											
Sub Units:	4	30											
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1										N	N	0	
Description - [** Comment to Railroad/Company **] INSPECTION OF TRACK INSPECTION RECORDS , G2 WALKS AT ATLANTIC TERMINAL , TRACKS 1 & 2, INCLUDING BROOK 1 & 2 INTERLOCKING. GATHER ALL OTHER DATA GEO CAR RECORDS, TRACK CHARTS, TRACK LENGHTS, PLATFORM LENGHTS, BUMPER INVENTORY, WITH THE NTSB. NO EXCEPTIONS TAKEN													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?			

Source Code C	File Number HQ-2017-1179	ID's of Accompanying Inspector(s)
------------------	-----------------------------	-----------------------------------