

652 Oliver Street Williamsport, PA. 17701 U.S.A.


This engine has been overhauled/rebuilt in accordance with the applicable Lycoming manuals. All applicable Federal Aviation Administration Airworthiness Directives and Lycoming Service Bulletins have been complied with. All parts have been inspected and have been determined airworthy to return to service. All accessories as part of the type certificate are either new or newly overhauled. Refer to enclosed Form ET001 for applicable accessory part numbers and serial numbers.

Engine Model: Serial #: Total Time: Work Order #: Date Completed: O-360-A1D RL-13741-36A 0.00 A-7770 1/30/03

Signed

Lycoming Service Center Williamsport/Lycoming Co. Airport Montoursville, PA 17754 Repair Station:

## Form No. 365



**ENGINE LOG** Serial No. Time Date **REPAIRS - ADJUSTMENTS - SERVICE - REMARKS** Hrs Min Signature 01, March 2003 - Tac. Time 1996.88 - Engine TT 0000.00 - Installed This License Da Engine 5/NRL- 13741- 36A in N9149V This Date. Engine Installed Using New Mounting Kits (4) J7402-1, OUH Carburetor P/N 71710, OUH Mays A/N 10-600614-1E + 10-600644-1F, New Fuel Pump PIN LW-15472, New Starter P/W 31A22470, New Hanness P/N LW-M-2403 Left + P/N LW-M-2404 Right, Serviceble Alternater PIWALY- 8520R, + OVH Governor PIN 34-828-14 See Mexical W.O. # 107680. All Fuel + Hoses Replaced @ This Time - See A/e Log. New Vacum Pump P/NZISCE Installed. Ground Run + Leak Check 6K Page Total **Brought Forward** All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Total to Date sate Number MUST be Shown.


				Name Home/Cell Phone #	Pilot
				ENGINE	100
	0	T	ime		LUG S
	Date	Hrs	Min	REPAIRS - ADJUSTMENTS - SERVICE	
4		-		SERVICI	E - REMARKS
				W.O.# 03-10-18 DATE 03- SIGNED A. B2W CORP. WINONA, MM	
				- Found OK - Scruiced En Filter Gun 10	· / · / / / / / / /
_	CI	448	110	Filter. Ground Runt L ge Total	gine with (0) ats A
			Pag	ge Total	call CK OK. Sec Wi
			Bro	ught Forward	All Repair Data Must Bear
			Tot	al to Date	Certificated Mechanic, and Certificate Number MUST

Latitude/Longitude		
mation		
Address		
Business Phone	 	
La La Cilana / Data		

## erial No.

Signature	License Number
	1 1 1 1 1 1 1
Non and the second	12 Den Comercia
Starley Co	
A Second	
d Oil + Filt	ter-Trench 1
roshel 80n	Dineral +
Ain 40.0. # 63-0	the second se
he Endorsement of a his Rating and	

ASA-SA-2



Se	erial No.		-	
n As Per N 77/80 #4 7 Inspected -6108 & Carburet Ondition. justed Mu er Shroud 1, 3, & 4 tywired. Good.	V6/80. Oil Safety or	License Number	1	
Bear the End	lorsement of a	-	-	-

ARKSnoroughly inspected as per existingand found to be in an airworthy condition.Total Time $2457,29$ hrs.Total Time $454.41$ hrs.me S.P.O.H. $1361.49$ hrs.
Total Time <u>454.41</u> hrs.
TATP
01

e er



le Number MUST de Snown.



**ENGINE LOG** Time Date REPAIRS - ADJUSTMENTS - SERVICE - REMARKS Hrs Min Serial No. en n Signature License 1 mo Number 4 105-22-3 2 10011 P 62 13 13 25 -09-0P 3 30 5 - MC 26. 1 23 and the all - a strates a certify that this 15123 · · · · · · · has been inspected in accordance with 8 Page Total Alat me inspection and has been **Brought Forward** All Repair Data Music De in airworthy Total to Date Certificated Mec Certificate Numb

Manufacturer Mooney Airen & Co. Serial 69\$\$26	Model M2¢C
Serial 69 \$\$26'	Registration Numbe
Date of Manufacture \$4-\$61-1969	

CRAL AD

		uality Man	S	QPN		Re
Aircraft Record General Info	rmation		brooch te	awo benefitiens	P-F017	
	~				15	Pag
Manufacturer Mooney Aires Serial 69\$\$26	alt Co.	Model M24	sc			
Serial 69 \$\$26		Registration Nu		9V		
Date of Manufacture	51- 1969					
Engine(s) currently installed:						
Manufacturer Lycomit	Model O	- 36\$ - 41D	Serial RL	- 13741 - 364		
Manufacturer	Model		Serial			
Propeller(s) currently installed:						
Manufacturer Hartzell Pro HUB Model	celler Inc.	Model HC-C	24R-18	P/F7497		
HUB Model	Serial CH	43\$2\$B	Serial	-		
Blade Model K67262	Serial	Serial		Serial	- F	
Blade Model K67252	Serial	Serial		_ Serial	F	
					m	ulator
					F	
			Last			
Fuel on Bo	pproach oard/Grade		Last Comm Position, Ti	unication me, Altitude		

<b>Propeller(s) currently installed:</b>		
Manufacturer Hartzell Pro	peller Inc.	Model HC-C2)
HUB Model	Serial CH4	3\$2\$8
Blade Model K67262	Serial	Serial
Blade Model K67252	Serial	Serial

	AVS		QPM #	
eneral Information			}-F(	017 Re
1 00 0			5	Page
44- \$1- 1969	- Model M2¢C - Registration Number ∠	N9149V		
stalled:				
Model O	- 36¢ - 41D Seri Seri	ial <u>RL - 1374</u>	- 36A	
installed: 211 Propeller Inc. Serial CH	Model HC-C2YR	2-18P/F74	-97	
Serial <u>CH</u> C2 Serial	<u>43¢2¢ 5</u> Serial	rial Serial		
262 Serial 52 Serial	Serial	Serial		
				mulator
T/O Direction	La Po	st Communication sition, Time, Altitude		

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspect Entries must be endorsed w
DATE				Technician or Repair Facility
UNIT M20C				
REGISTRAT N9149V	ION		21	CA AIR
DATE	MEG			The Island Citv's FBO
05-22-08	MFG. Mooney	7	MOD	DEL
			M20	S/N 690026 AIRCRAFT LOG ENTRY : M20C INSPECTION GUIDE, 04-30 3-2014. C/W A.D. 73-21-01 Dec.
DUE PRIOR TO DUE PRIOR TO REPLACED SCA STRIPPED, PAIN PROPELLER, PN 835-54(P), IN ACC ALTERNATOR D COMPLIED WIT I certify that with refound to be airworth ORDER have been for the second sec	N OF HEIM BE TAC. TIME 27 AT TUBE BETW NTED WITH A N: HC-C2YK-11 CORDANCE W ORIVE BELT, I H AND ALL FO spect to the work by in accordance inspected, found	ARING EN 06.14. RE WWEN MU CID PROC B, SN: CH- /ITH INST PN: 37A197 OUND TO k performed with curren to be airwo	ND INTO BEL ND INTO BEL PLACED MIS JFFLER & CA DF # 344 & RE 6751E. INSTA 011007, DAT 73-376. AIRC BE SATISFAC I on the aircraft, it regulations of rthy and are are	3-2014. C/W A.D. 73-21-01 DATED ONTROLS & (c) BY PERFORMING ON OF ENGINE MOUNT. C/W A. A.Ds ARE DUE NEXT PRIOR TO A ECTION AND LUBE, II C/W WHE L CRANK. PART II DUE PRIOR TO SING SCREWS & STOPPED DRIN RB INTAKE. REMOVED BATTE PLACED. REMOVED SPINNER, I ALLED STC # SA02414CH-D, PN: H ED 01-10-07, SEE 337 & WGT & BA CRAFT GROUND RUN, OPERATIO CTORY. ************************************

vith Naty. (Sec	<b>, Tes</b> me, Ra back	ts, Repa ating and pages for	Certificate other spe	Alterat e Number ecific entri	ions of ies.)
30-90 AS D 10-10- G RETI A.D. 76-0 A/CTT EN PAR TO TA ILLED ERY BO BULKI HC-C2 BAL TH	TSO N/A S AMM 73, PAR ACTIO 7-12R1 & TAC, 7-12R1 & TAC, 7-	W 1( Win Ph CYCLES N/A CYCLES N/A CYCLES N/A ENDED. C A. (a) BY 1 DATED 08 2606.14. (C) V AND PAI E 2606.14. (C) V AND PAI E 2606.14. (C) V AND PAI E 2606.14. (C) V AND PAI E 2606.14. (C) ANED COI ANED COI ANED COI COI COI COI COI COI COI COI	in Air / 1 6 Galewski 1000a, MN. 5 # 507 452-2 TAC 2506.14 C/W FAR 9 LUBRICAT RIGGING 3-30-77 BY C/W MOO RT III COI PARTS I & E #2 CYLL RROSION, LL N: CH4302 ACED	B <sub>2</sub> W i Dr. 55987 2220 TT 2506.14 1.207(d) TING G. C/W/ OPS NEY RRECT & II INDER. 0B &	
ove, that Only th details of	they we ose item of the We	re repaired, s identified ORK are on worthiness a	on the WO	RK Air/	

Entries must be endorsed with Name, Rating and Certificate Number of TIME SERVICE Technician or Repair Facility. (See back pages for other specific entries.) DATE 2998 . ch 5-09-08 E Genn -0 Re A a · (Dal) 2015-26 Anca I certify that this has been inspected in accordance with mul inspection and has been an determined to be in airworthy condition AP -ype of Operation Recurrent ERe-Qualification E Transition E S Dep. Point & Date Flight Plan Flight Information Radar Coverage Involved FAR Conducted LL Type of Approx