

Photo 1 – Airframe logbook, annual inspection

TE _	Inst	vice Bulletins, tructions & A	Letters, D Notes
	N6427P (Engine)	DAYTONA	7/12/2018
	Piper PA-24-250 S/N: 24-1537	AIRCRAFT SERVICES	Tach: 1024.1
	Engine M/N: O-540-A1C5	S/N: L-1437-40	Eng TT: 3422.0 Eng TSMOH: 1268.0
	Performed the following mainte	enance: pection referencing the Piper PA-24-250 M	
	2. Performed a compression	test with the following results: #1 65/80	, #2 76/80, #3 68/80, #4 75/80, #5
	a 1 to 1 and alcohold the	Oil Filter Screen as required.	C II 4 Cydindare
_	4. Removed the Primer Line	es, fabricated and installed new Printer Lin	
	I certify that this Engine has bee	eks found to be satisfactory. en inspected in accordance with an Annua k performed in accordance with the curr	l inspection and was determined to ent regulations of the FAA and is
	approved for return to service. D	etails are on the at this repair content	er WO #SC10306.
	Daytona Aircraft Services, Inc.	. Authorized Signature	
	561 Pearl Harbor Drive	Admorate	Jake Clemens A&P
	Daytona Beach, Florida 32114	END	

Photo 2 – Engine logbook, annual inspection




Photo 3 – Propeller logbook