


A. Customer Information - *THIRD PARTY WORKORDER*

	2450 Derry Rd East Hangar #9, Bay C	W.O.#	W.O.#
	Mississauga, ON L5S 1B2	W.O.# 0017-Nov11	W.O.#
T: 905-405-1446 F: (905) 405-9919	A/C Reg: N168SL	Model: Piaggio	A/C S/N: 1139
Customer: Avantair	P.O.# RO11-1139-62921	Originator: J Ruth	Date: 15-Nov-11
Address: 4311 General Horward Dr. Clearwater Florida 33762	Contact: Jim Yotas	Ph. #: 888-349-7180	

B. Discrepancy

<input type="checkbox"/> Scheduled Maintenance	Arrow AWC #: na	Entered By: Jim Ruth	Date: 15-Nov-11
--	-----------------	----------------------	-----------------

Left power lever will not go into beta or reverse.

Customer Authorization for work to be completed:	NA see PO	Date:
(Cross out if not required)	(Print Name)	(Initial)

C. Rectification

	Date	Mech
Left power lever cleaned, inspected and lubricated IAW Piaggio II AMM 76-10-00 and P&W MM 72-00-00. Ground runs performed and system checked serviceable IAW Piaggio AMM 71-00-00.	Nov 15/2011	[Redacted]
<input type="checkbox"/> Scheduled Maintenance	Arrow AWC #: NA	Closed By: [Redacted]
		Date: Nov 15/2011

D. Parts Required

Description	P/N	QTY	BATCH #	S/N OFF	S/N ON


E. Certification

INDEPENDENT INSPECTION I have conducted an independent inspection for correct assembly & locking of any parts distributed, including an operational check for proper sense & range of motion of the engine or flight control by the maintenance performed.		INSPECTION Inspection has been performed in accordance with the standards of Airworthiness	
Signature	ACA	Signature	[Redacted]
Date		Date	Nov 15/2011
		ACTC	4420.6
		ACTC	3411

F. Quality Assurance:

Reviewed By: [Redacted]	Date: Nov 15/11	Page 1 of 2
-------------------------	-----------------	-------------

A. Customer Information - *THIRD PARTY WORKORDER*

 2450 Derry Rd East Hangar #9, Bay C Mississauga, ON L5S 1B2 T: 905-405-1446 F: (905) 405-9919	W.O.#		W.O.#	
	W.O.# 0017-Nov11		W.O.#	
	A/C Reg: N168SL	Model: Piaggio	A/C S/N: 1139	
	P.O.# RO11-1139-62921	Originator: J Ruth	Date: 15-Nov-11	
Customer: Avantair	Address: 4311 General Horward Dr. Clearwater Florida 33762		Contact: Jim Yotas	Ph. #: 888-349-7180

B. Discrepancy


<input type="checkbox"/> Scheduled Maintenance	Arrow AWC #: na	Entered By: Jim Ruth	Date: 15-Nov-11
--	-----------------	----------------------	-----------------


Excessive generator amperage split -50A Approximate on gnd, 110A airborne.

Customer Authorization for work to be completed: SEE PO. Date: 15-Nov-11
 (Cross out if not required) (Print Name) (Initial)

C. Rectification

Left and Right Generator control units removed, ground points cleaned, units swapped and reinstalled. Engines operated and gnd idle and power, loads found to now be within 10% at all power and load settings. Work completed IAW Piaggio II AMM 24-30-00.



<input type="checkbox"/> Scheduled Maintenance	Arrow AWC #: NA	Closed By: 	Date: Nov 15/2011
--	-----------------	---	-------------------

D. Parts Required

Description	P/N	QTY	BATCH #	S/N OFF	S/N ON

E. Certification

INDEPENDENT INSPECTION I have conducted an independent inspection for correct assembly & locking of any parts distributed, including an operational check for proper sense & range of motion of the engine or flight control by the maintenance performed.		I certify that this work has been performed in accordance with the standards of Airworthiness.	
Signature	ACA	Signature	
Date	ACA	Date	Nov 15/2011
ACTC #	4420.6	ACTC #	3411

F. Quality Assurance:	Reviewed By: 	Date: Nov 15/11	Page 1 of 2
-----------------------	--	-----------------	-------------