



Highway Accident Brief: Pedetsrian SIR

Scene and vehicle photographs

Manhattan, New York #1

HWY17SH003

(6 pages)



Photo #1: Intersection of East Houston Street and D Street, looking north from Columbus Street.



Photo #2: Close-up of marked crosswalks and concrete center median.



Photo #3: Interior view of transit bus driver's seating position.



Photo #4: Interior view of front of bus and location of standing passenger during crash.



Photo #5: Interior view of signs informing passengers not to speak with driver or stand forward of white line while transit bus is in motion.



Photo #6: The driver's view as he approached the intersection.




Photo #7: The driver's view of the intersection while awaiting traffic signal light to change.



Photo #8: View of exemplar transit bus as it approaches the turn from D Street to East Houston Street.



Photo #9: Exemplar transit bus executing the turn onto East Houston Street with pedestrian walking southbound in marked crosswalk.



Photo #10: Exemplar transit bus at point where pedestrian in crosswalk is visible to driver.