



Materials Laboratory 15 - Exhibit No. 15A - Photo 1. View looking forward at a portion of the front spar lower chord fracture. The bracket indicated the location of a fatigue crack.