



Materials Laboratory 15 - Exhibit No. 15B - Photo 5.
SEM photograph of the features within the deformed
crescent adjacent to the hole on the upper surface.
Remnants of the mud-cracked oxide deposits are also
visible on the surface. (334X)