

B-3-B Conductor Valve Test

82797

A-end	Verified
B-end	Verified

43346

A-end	Verified
B-end	Verified

82761

A-end	Verified
B-end	Plugged due to damage

82644

A-end	Verified
B-end	Verified, now plugged

82776

A-end	Inaccessible
B-end	Inaccessible

82981

A-end	Verified
B-end	Verified