



**DCA17FR003**  
**SEPTA**  
**Collision of Trolley Car 9085 and 9101**  
**38th Street and Lancaster Avenue**  
**Philadelphia, PA**  
**January 4, 2017**

## **Attachment 1**

**LRV 9085 and 9101 Pre-Trip Inspection Record**

# LRV Pre-trip/Relief Check List

**Check if any item is defective**

- 1. Brakes/Air Pressure
- 2. Sanders
- 3. Horns/Gong
- 4. Lights
- 5. Wipers
- 6. Doors
- 7. Radio
- 8. P. A. System
- 9. Destination Signs
- 0. Pocket Schedules
- 1. Farebox
- 2. Graffiti
- 3. Body Damage
- 4. Cleanliness
- 5. Emergency Equipment
- 6. CBTC
- 7. Speedometer
- 8. Other

Operator Signature 

Account # 19260

Relief Operator  
Signature \_\_\_\_\_

Account # \_\_\_\_\_


Route/Block 10-9055

Date 4 Jan 16 Trolley 9085




**Note Scratches with a Line (-)  
and Dents with an ( X )**


**Front**




**Rear**



**Right Side**



**Left Side**



# LRV Pre-trip/Relief Check List

**Check if any item is defective**

- 1. Brakes/Air Pressure
- 2. Sanders
- 3. Horns/Gong
- 4. Lights
- 5. Wipers
- 6. Doors
- 7. Radio
- 8. P. A. System
- 9. Destination Signs
- 10. Pocket Schedules
- 11. Farebox
- 12. Graffiti
- 13. Body Damage
- 14. Cleanliness
- 15. Emergency Equipment
- 16. CBTC
- 17. Speedometer
- 18. Other

Operator Signature 

Account # 17839

Relief Operator  
Signature \_\_\_\_\_

Account # \_\_\_\_\_


Route/Block 10-9062

Date 1/4/17 Trolley 7101




**Note Scratches with a Line (-)  
and Dents with an ( X )**


**Front**



**Rear**



**Right Side**



**Left Side**

