

**RRD18MR001
Amtrak
Collision
Cayce, SC
February 4, 2018**

Attachment 10
Train list F777, 34 Auto Rack Cars
(Compiled by NTSB)

CSX Auto-Rack Airbrake test 2/5/2018

2nd locomotive #37

- | | | |
|------------------------------------|--------------------|---------------------|
| 1. SP 516546 ✓ | 26. TTGX 940938 ✓ | } Pissing air |
| 2. ETTX 810122 ✓ | 27. TTGX 990604 ✓ | |
| 3. ETTX 909843 ✓ | 28. TTGX 963931 ✓ | |
| 4. ETTX 802691 ✓ | 29. TTGX 991210 ✓ | |
| 5. ETTX 706423 ✓ | 30. TTGX 964655 ✓ | |
| 6. ETTX 703386 ✓ | 31. 964409 ✓ | |
| 7. 700695 ✓ | 32. 986020 ✓ | |
| 8. 853084 ✓ | 33. 254187 ✓ | } BEND
Door open |
| 9. PW 104366 ✓ | 34. 35. | |
| 10. TTGX 961907 ✓ | 36. | |
| 11. TTGX 704874 ✓ | | |
| 12. TTGX 976060 ✓ | | |
| 13. 971353 ✓ | | |
| 14. ETTX 703966 ✓ | | |
| 15. TTGX 978413 - Broken Cat lever | | |
| | | |
| 16. TTGX 956997 ✓ | | |
| 17. TTGX 977206 ✓ | | |
| 18. TTGX 942388 ✓ | | |
| 19. TTGX 987792 ✓ | | |
| 20. TTGX 695284 ✓ | | |
| 21. TTGX 995686 ✓ | | |
| 22. TTGX 693474 ✓ | | |
| 23. TTGX 973876 ✓ | | |
| 24. TTGX 983772 ✓ | | |
| 25. TTGX 993176 ✓ | | |

When enumerating the car count on the hand written list an error was made between cars six and seven. There is a car between these two numbers. There are 34 cars on this list.

leakage test
5374 (L)
751

02/06/2018