

**RRD18MR001
Amtrak
Collision
Cayce, SC
February 4, 2018**

Attachment 7
CSXT 36 Daily Inspection Record



LOCOMOTIVE WORK REPORT (5001B)

INSTRUCTIONS — EACH LOCOMOTIVE UNIT shall be inspected in accordance with RULE 229 of the LAWS, RULES and INSTRUCTIONS for inspection and testing of locomotives other than steam. Lines 1 to 4 must always be filled out.

LOCOMOTIVE INITIAL: _____
LOCOMOTIVE NUMBER: _____

LOCOMOTIVE WORK REPORT (5001B) RETAINED ON LOCOMOTIVE UNTIL:
- LOCOMOTIVE ENTERS A MECHANICAL FACILITY
- LOCOMOTIVE REACHES AN OUTLYING FACILITY WITH DEFECTS (THIS FORM MUST THEN BE DATA-FAXED TO A DESIGNATED MECHANICAL FACILITY)

- 1. TRAIN NUMBER _____ DISPATCHED FROM _____ DATE _____
- 2. BRAKE PIPE PRESSURE _____ LBS. MAIN RESERVOIR PRESSURE _____ LBS.
- 3. CONDITION OF RADIO - GOOD - REPORTED - NOT EQUIPPED LOCO. NUMBER _____ SERIAL NUMBER _____
- 4. CONDITION OF SPEED INDICATOR — UNIT NUMBER _____ ACCURATE OR _____ M.P.H. SLOW-FAST AT _____ M.P.H. REPORTED

ITEM	LOCO. NO.	REPAIRS NEEDED	REPORTED BY	REPAIRED BY
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				

SIGNATURE OF EMPLOYEE _____

SIGNATURE OF EMPLOYEE _____

- A. _____ D. _____
- B. _____ E. _____
- C. _____ F. _____

* DEFECTS MUST BE REPORTED TO MECHANICAL DEPT. *



CALENDAR DAY INSPECTION — MUST BE COMPLETED FOR EACH LOCOMOTIVE (5001A)

INIT. NO.

LOCO. CSXT 36 LOCATION Calico DATE 2-3-18 TIME 2005

ITEM	DEFECTS NOTED	REPAIRED BY	TYPE OF REPAIR
1			
2			
3			
4			
5			
6			

CALENDAR DAY INSPECTION MADE BY: _____

ORIGINAL — KEPT ON FILE AT OFF DUTY LOCATION PART 2 (COPY) — LEAVE ON LOCOMOTIVE