

**RRD18MR001  
Amtrak  
Collision  
Cayce, SC  
February 4, 2018**

**Attachment 9**  
CSXT 0130 Daily Inspection Record



# LOCOMOTIVE WORK REPORT (5001B)

CSX FORM 5001-RM  
REV. 4-99  
S/C # 48059437351

INSTRUCTIONS — EACH LOCOMOTIVE UNIT shall be inspected in accordance with RULE 229 of the LAWS, RULES and INSTRUCTIONS for inspection and testing of locomotives other than steam. Lines 1 to 4 must always be filled out.

LOCOMOTIVE	
INITIAL	NUMBER
CS XT	130 3C

LOCOMOTIVE WORK REPORT (5001B) RETAINED ON LOCOMOTIVE UNTIL:

- LOCOMOTIVE ENTERS A MECHANICAL FACILITY
- LOCOMOTIVE REACHES AN OUTLYING FACILITY WITH DEFECTS (THIS FORM MUST THEN BE DATA-FAXED TO A DESIGNATED MECHANICAL FACILITY)

TRAIN NUMBER F777-03 DISPATCHED FROM Cayce, SC DATE 2-3-18


BRAKE PIPE PRESSURE 96 LBS. MAIN RESERVOIR PRESSURE 137 LBS.

CONDITION OF RADIO - GOOD - REPORTED - NOT EQUIPPED\* LOCO. NUMBER 130 SERIAL NUMBER \_\_\_\_\_

CONDITION OF SPEED INDICATOR — UNIT NUMBER 130 ACCURATE OR \_\_\_\_\_ M.P.H. SLOW-FAST AT \_\_\_\_\_ M.P.H. REPORTED \_\_\_\_\_

ITEM	LOCO. NO.	REPAIRS NEEDED	REPORTED BY	REPAIRED BY
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				

SIGNATURE OF EMPLOYEE \_\_\_\_\_ SIGNATURE OF EMPLOYEE \_\_\_\_\_

A.  D. \_\_\_\_\_

B. \_\_\_\_\_ E. \_\_\_\_\_

C. \_\_\_\_\_ F. \_\_\_\_\_


\* DEFECTS MUST BE REPORTED TO MECHANICAL DEPT. \*



## CALENDAR DAY INSPECTION — MUST BE COMPLETED FOR EACH LOCOMOTIVE (5001A)

INIT. CS XT NO. 130 LOCATION Cayce, SC DATE 2-3-18 TIME 2015

ITEM	DEFECTS NOTED	REPAIRED BY	TYPE OF REPAIR
1			
2			
3			
4			
5			
6			

CALENDAR-DAY INSPECTION MADE BY: 

ORIGINAL — KEPT ON FILE AT OFF DUTY LOCATION PART 2 (COPY) — LEAVE ON LOCOMOTIVE