



Chart 4.29 Seat Damage and Floating Victims

- Minimal (17)
- Moderate (33)
- Severe (28)
- Destroyed (157)
- Fragmented (185)
- Floating Victim (88)

Notes:
1. Seating positions reflect emergency seating. Passengers may have
changed seats during a 100% drill prior to the accident.
2. The 179th stowaway was seated immediately prior to the collision.
3. The 180th was not recovered.

Medical/Forensic 19 - Exhibit No. 19B - Chart 4.29 Seat Damage and Floating Victims