



**Motor Carrier Attachment 21:**  
**Accident Driver's Roadside Inspections**  
**Oxnard, California**  
**HWY15MH006**  
( 5 pages)

# DRIVER/VEHICLE EXAMINATION REPORT



**CHP 407F/343A-Aspen**  
**California Highway Patrol**  
 [REDACTED]  
**Sacramento, CA 95811**  
**Phone: [REDACTED] Fax: [REDACTED]**

**Report Number: CA3RLC002905**  
**Inspection Date: 2014-11-05**  
**Start Time: 16:47 End Time: 17:03**  
**Insp. Level: III - Driver/Credential Inspection**  
**HM Inspection Type: X**

**THE GROWERS COMPANY INC**  
 [REDACTED]  
 SOMERTON, AZ 85350-3170  
**USDOT#: 00718118**      **Phone#: [REDACTED]**  
**MC/MX#:**                      **Fax#:**  
**State#: 120298**

**Driver: [REDACTED]**  
**License #: [REDACTED] State: AZ**  
**Date of Birth: [REDACTED]**  
**CoDriver:**  
**License#: State:**  
**Date of Birth:**

**Location: DESERT HILLS CVEF**      **MilePost: 15.65**                      **Shipper:**  
**Highway: I-10**                      **Origin: CA**                      **Bill of Lading:**  
**County:**                      **Destination: AZ**                      **Cargo:**

VEHICLE IDENTIFICATION										
Unit	Type	Make	Year	State	License #	Company #	Vin #	GVWR	CVSA#	OOS#
1	TT	FORD	1990	AZ	AA[REDACTED]	TK219/WHT	1FDYR90LXLV[REDACTED]	0		
2	ST	UNK	1960	AZ	M4[REDACTED]	FB	0112160	0		

**BRAKE ADJUSTMENTS**

Axle #  
 Right  
 Left  
 Chamber

VIOLATIONS									
Section Code	Federal Code	Type	Unit	OOS	Citation #	Verify	Crash	Violation	Discovered
<b>Special Checks: Size &amp; Weight,</b>									

**State Information:** Beat/Sub Area: 880; Veh #1 Type: 25; Veh #2 Type: 31; Regulated Vehicle: Y; Pre-Cleared Vehicle: N;

This is not a citation. Please read the instructions on the reverse side of this form.  
 Note: \* Owner Responsibility

**Report Prepared By:** [REDACTED]      **Badge #:** 13586      **Copy Received By:** [REDACTED]  
 X \_\_\_\_\_                      X \_\_\_\_\_



## DRIVER/VEHICLE EXAMINATION REPORT



**CHP 407F/343A-Aspen**  
**California Highway Patrol**  
 [REDACTED]  
 Sacramento, CA 95811  
 Phone: [REDACTED] 50 Fax: (9 [REDACTED]

**Report Number:** CA39R3009695  
**Inspection Date:** 2013-10-28  
**Start Time:** 10:13 **End Time:** 10:43  
**Insp. Level:** I - Full Inspection  
**HM Inspection Type:** X

**HARVEST MANAGMENT LLC**  
 [REDACTED]  
 SOMERTON, AZ 85350  
**USDOT#:** 01076796  
**MC/MX#:**  
**State#:**

**Phone#:** (909) 997-9999  
**Fax#:**

**Driver:** [REDACTED]  
**License #:** [REDACTED] **State:** AZ  
**Date of Birth:** [REDACTED]  
**CoDriver:**  
**License#:** **State:**  
**Date of Birth:**

**Location:** SIDEWINDER PLATFORM **MilePost:** **Shipper:**  
 SCALE  
**Highway:** I-8 WEST BOUND **Origin:** SOMERTON, AZ **Bill of Lading:**  
**County:** **Destination:** SOMERTON, AZ **Cargo:** BOBTAIL

VEHICLE IDENTIFICATION										
Unit	Type	Make	Year	State	License #	Company #	Vin #	GVWR	CVSA#	OOS#
1	TT	FORD	1992	AZ	AB [REDACTED]	WHT 415	1FTYA95X8 [REDACTED]	80000	19362650	

BRAKE ADJUSTMENTS			
Axle #			
Right		0	1
Left			2
Chamber		C-20	C-30

VIOLATIONS									
Section Code	Federal Code	Type	Unit	OOS	Citation #	Verify	Crash	Violation Discovered	
1232(A) CCR /001	396.3A1	C	1	0		N	0	General maintenance--396.3 (a)(1) X2 L/S AIR BAG FRAILING	

**Special Checks:** Size & Weight,  
**State Information:** Beat/Sub Area: 880; Veh #1 Type: 25; Regulated Vehicle: Y; Pre-Cleared Vehicle: N;

This is not a citation. Please read the instructions on the reverse side of this form.  
 Note: \* Owner Responsibility

**Report Prepared By:** [REDACTED] **Badge #:** A15844 **Copy Received By:** [REDACTED]  
 X \_\_\_\_\_ X \_\_\_\_\_



## DRIVER/VEHICLE EXAMINATION REPORT



**CHP 407F/343A-Aspen**  
**California Highway Patrol**  
 [REDACTED]  
**Sacramento, CA 95811**  
**Phone: [REDACTED] Fax: [REDACTED]**

**Report Number: CA39QZ001775**  
**Inspection Date: 2013-05-20**  
**Start Time: 14:54 End Time: 15:03**  
**Insp. Level: I - Full Inspection**  
**HM Inspection Type: X**

**HARVEST MANAGMENT LLC**

SOMERTON, AZ 85350

**USDOT#: 01076796**

**MC/MX#:**

**State#:**

**Location: SIDEWINDER PLATFORM MilePost:**  
SCALE

**Highway: I-8 WEST BOUND**

**County:**

**Phone#: [REDACTED]**  
**Fax#: [REDACTED]**

**Origin: YUMA, AZ**  
**Destination: CA**

**Driver: [REDACTED]**

**License #: [REDACTED] State: AZ**

**Date of Birth: [REDACTED]**

**CoDriver:**

**License#: State:**

**Date of Birth:**

**Shipper:**

**Bill of Lading:**

**Cargo:**

**VEHICLE IDENTIFICATION**

Unit	Type	Make	Year	State	License #	Company #	Vin #	GVWR	CVSA#	OOS#
1	TT	STRG	2001	AZ	AFC1656	WHT	2FWBA2A821A [REDACTED]	80000	18654928	

**BRAKE ADJUSTMENTS**

Axle #	Right	Left	Chamber
0			C-20
1			C-30

**VIOLATIONS**

Section Code	Federal Code	Type	Unit	OOS	Citation #	Verify	Crash	Violation Discovered
<b>Special Checks: Size &amp; Weight,</b>								

**State Information:** Beat/Sub Area: 880; Veh #1 Type: 25; Regulated Vehicle: Y; Pre-Cleared Vehicle: N;

This is not a citation. Please read the instructions on the reverse side of this form.  
Note: \* Owner Responsibility

**Report Prepared By:**

**Badge #:**  
A13374

**Copy Received By:**

X \_\_\_\_\_

X \_\_\_\_\_



CA39QZ001775

# DRIVER/VEHICLE EXAMINATION REPORT



**CHP 407F/343A-Aspen**  
**California Highway Patrol**  
 [REDACTED]  
**Sacramento, CA 95811**  
**Phone:** [REDACTED] **Fax:** [REDACTED]

**Report Number:** CA39R3008468  
**Inspection Date:** 2013-05-17  
**Start Time:** 11:35 **End Time:** 11:53  
**Insp. Level:** I - Full Inspection  
**HM Inspection Type:** X

**HARVEST MANAGEMENT LLC**  
 [REDACTED]

SOMERTON, AZ 85350

**USDOT#:** 01076796

**Phone#:** [REDACTED]

**MC/MX#:**

**Fax#:**

**State#:**

**Location:** SIDEWINDER PLATFORM SCALE **MilePost:**

**Highway:** I-8 WEST BOUND

**Origin:** SOMERTON, AZ

**County:**

**Destination:** SIDEWINDER, CA

**Driver:** [REDACTED]

**License #:** [REDACTED] **State:** AZ

**Date of Birth:** [REDACTED]

**CoDriver:**

**License#:** **State:**

**Date of Birth:**

**Shipper:**

**Bill of Lading:**

**Cargo:** EMPTY

**VEHICLE IDENTIFICATION**

Unit	Type	Make	Year	State	License #	Company #	Vin #	GVWR	CVSA#	OOS#
1	TT	STRG	2001	AZ	A [REDACTED]	WHT TK416	2FWBA2A821A120754	80000		

**BRAKE ADJUSTMENTS**

Axle #	Right	Left	Chamber
	0	1	
			C-20
			C-30

**VIOLATIONS**

Section Code	Federal Code	Type	Unit	OOS	Citation #	Verify	Crash	Violation Discovered
1232(A) CCR /016	393.209D	C	1	0	1 [REDACTED]	N	0	FRONT DRAG LINK BALL JOINT WORN

**Special Checks:** Size & Weight,

**State Information:** Beat/Sub Area: 880; Veh #1 Type: 25; 44467HD; 215; 17454; Regulated Vehicle: Y; Pre-Cleared Vehicle: N;

This is not a citation. Please read the instructions on the reverse side of this form.  
 Note: \* Owner Responsibility

**Report Prepared By:**

**Badge #:**  
A8867

**Copy Received By:**

X \_\_\_\_\_

X \_\_\_\_\_



CA39R3008468