



Motor Carrier Attachment – Accident Vehicle Maintenance File

Biloxi, MS

HWY17MH010

(21 pages)

**Work Order Detail
for Asset 8421**

Work Order: **DAL001-2017-143 WINDSHIELD**
 Status: **WORK FINISHED**

Dept: **CHARTER - CHARTER**
 Asset No: **(8421) 2016 VAN HOOL CX45**
MOTORCOACH-2016-VAN HOOL-CX45

Serial No: **YE2XC81B8G** License: **3** Warranty: **NO**

Asset No:	2016-VAN HOOL-CX45	Opened By:		Date In:	01/31/2017 11:36
Eq Type:	2016-VAN HOOL-CX45	Current Equip Status:		Date Due:	02/01/2017 11:36
Job Type:	REPAIR	Account:	MOTORCOACH	Opened:	01/31/2017 11:36
Meter 1:	52,163.00	Reference WO:		Finished:	03/03/2017 10:56
Meter 2:	0.00	Estimated Hours:	0.00	Closed:	
Shop Hrs:	96.00	User Hours:	0.00	Warranty Expire:	
Priority:	4 - 24 HOUR TURNAROUND	Accident:			
Incident:		Project:			

Non Service Request Tasks			
Task: (001-000) Diagnose/Troubleshoot			Warranty: NO
WAC: 05 - PREVENTATIVE MAIN Reason: BD - BREAKDOWN			
Work Class: 2 - NON-SCHEDULEI Comments:			
Task Notes			
3-1-2017 10:42AM A/C NOT COOLING			
Labor			
03/03/2017 12:00:(Emp: (10008)		Labor Hrs Cost
			1.50 60.00
03/03/2017 12:00:((10009)		1.00 40.00
Task: (045-070) Accessory Belts			Warranty: NO
WAC: 03 - REPLACE PART Reason: BD - BREAKDOWN			
Work Class: 2 - NON-SCHEDULEI Comments:			
Task Notes			
2-16-2017 2:41PM REPLACED BELT TENSIONER			
Labor			
03/03/2017 12:00:(Emp: (10009)		Labor Hrs Cost
			1.50 60.00
Parts			
		Qty Issued Iss Price	Total Cost
(A4712001570-0) ENGINE; BELT TENSIONER			1.00 183.31 183.31
Task: (071-010) Body			Warranty: NO
WAC: 11 - PAINT PREP AND REP Reason: BD - BREAKDOWN			
Work Class: 2 - NON-SCHEDULEI Comments:			
Labor			
03/03/2017 12:00:(Emp: (10001)		Labor Hrs Cost
			6.00 240.00
03/03/2017 12:00:((10002)		6.00 240.00
Task: (071-030) Glass			Warranty: NO
WAC: 03 - REPLACE PART Reason: BD - BREAKDOWN			
Work Class: 2 - NON-SCHEDULEI Comments:			
Labor			
02/22/2017 12:00:(Emp: (10001)		Labor Hrs Cost
			2.00 80.00
02/22/2017 12:00:((10002)		2.00 80.00

Work Order Detail

Work Order: **DAL001-2017-143**

Parts	Qty Issued	Iss Price	Total Cost
(11469436-0) RUBRAIL ENTRANCE DOOR	1.00	82.62	82.62
(08609-0) WINDOW WELD	2.00	17.69	35.38
(10696948-0) BODY; WINDSHIELD TRANSLITE C2000	1.00	149.00	149.00
(10890283-0) LIGHTING SYS; H9 BULB	2.00	10.94	21.87
(10973782-0) BODY; DOOR BUTTON	1.00	3.46	3.46
(11017007-0) LIGHTING SYS; LIGHT , ADAPTIVE AIMING RH	1.00	106.99	106.99

Overhead

Small Parts - Labor: **0.00** Tools: **0.00** Total Overhead Costs: **20.00**
 Small Parts - Parts: **0.00** Overhead Costs: **20.00**

Messages

Unit Is 8 Days Late For Pm Service Pm-A - Due Date 02/23/2017
 Unit Is Overdue 46163 Life Miles On Meter 1 For Service Pm-A
 - Life Meter 1 Due At 6000
 Unit Is 8 Days Late For Pm Service Pm-C - Due Date 02/23/2017

WO Notes

1-31-2017 11:37AM REPLACE LEFT WINDSHIELD

Comments:
 WINDSHIELD

Internal Parts Cost:	\$582.63
Internal Labor Cost:	\$800.00
Commercial Parts Cost:	\$0.00
Commercial Labor Cost:	\$0.00
Commercial Misc Cost:	\$0.00
Commercial Tax & Markup:	\$0.00
Equipment Usage Costs:	\$0.00
Overhead Costs:	\$20.00
Internal Total:	\$1,402.63
Commercial Total:	0.00
Work Order Total:	\$1,402.63

Work Order Detail for Asset 8421



Work Order: **DAL001-2017-143 WINDSHIELD**
Status: **OPEN**

Dept: **CHARTER - CHARTER**

Asset No: **(8421) 2016 VAN HOOL CX45**
MOTORCOACH-2016-VAN HOOL-CX45

Serial No: **YE2XC81B8G** License:
3

Asset No:	Opened By:	KKIFER	Date In:
Eq Type: 2016-VAN HOOL-CX45	Current Equip Status:		Date Due:
Job Type: REPAIR	Account:	MOTORCOACH	Opened:
Meter 1: 52,163.00	Reference WO:		Finished:
Meter 2: 0.00	Estimated Hours:	0.00	Closed:
Shop Hrs: 0.00	User Hours:	0.00	Warranty Expire:
Priority: 4 - 24 HOUR TURNAROUND	Accident:		
Incident:	Project:		

Non Service Request Tasks

Task: **(001-000) Diagnose/Troubleshoot**

WAC: Reason: **BD - BREAKDOWN**
Work Class: **2 - NON-SCHEDULED** Comments:

Task Notes

FOUND OUTSIDE AMBIEN TEMP SENSOR WIRES BROKEN
3-1-2017 10:42AM A/C NOT COOLING *REPAIR WIRING AND CLEAN FILTERS*

Task: **(045-070) Accessory Belts**

WAC: **03 - REPLACE PART** Reason: **BD - BREAKDOWN**
Work Class: **2 - NON-SCHEDULED** Comments:

Task Notes

DONE
2-16-2017 2:41PM REPLACED BELT TENSIONER

Parts	Qty Issued	Iss P
(A4712001570-0) ENGINE; BELT TENSIONER	<i>DONE</i>	
	1.00	183

Task: **(071-030) Glass**

WAC: **03 - REPLACE PART** Reason: **BD - BREAKDOWN**
Work Class: **2 - NON-SCHEDULED** Comments:

Labor	Labor H
02/22/2017 12:00:00AM Emp: (10001)	2.
02/22/2017 12:00:00AM (10002)	2.

Parts	Qty Issued	Iss P
(11469436-0) RUBRAIL ENTRANCE DOOR	1.00	82
(08609-0) WINDOW WELD	2.00	17
(10696948-0) BODY; WINDSHIELD TRANSLITE C2000	1.00	149
(10890283-0) LIGHTING SYS; H9 BULB	2.00	10
(10973782-0) BODY; DOOR BUTTON	1.00	3
(11017007-0) LIGHTING SYS; LIGHT , ADAPTIVE AIMING RH	1.00	106

Overhead

Small Parts - Labor: 0.00	Tools: 0.00	Total Ove
Small Parts - Parts: 0.00	Overhead Costs: 20.00	



Exterior:

All lights working
 Body damage
 Wipers

Tires:

New Spare Yes ___ No ___
LF 15/32 RF 15/32
LO 14/32 RO 13/32
LI 13/32 RI 12/32
LT 9/32 RT 14/32

Fluids:

Oil
Coolant
Transmission
P/S Fluid Temsa / Mini
Washer Fluid

All tires are at 115 PSI

Wash radiator, condenser

DEF (If applicable)

Interior:

Driver Light
Step Light
Restroom Light
Dash Warning Lights
AC/Heater working
Verify Radio,DVD,Monitors and PA are working

Undercarriage:

Fluid Leaks
Air Leaks (Use soapy water)
Wheel seals
Visual Brake inspection
Lube U-Joints, King Pins, and Gear box
Inspect Tire wear

Part usage:

QTY: Part Number:

Comments:

Date: 2/7/17

Bus # 8421

Mileage: 60160

Inspector: [Redacted]

Date: _____

Bus ready for service: YES NO _____



Exterior:

All lights working
 Body damage
 Wipers

Tires:

New Spare		Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
LF	15/32	RF	16/32
LO	12/32	RO	13/32
LI	14/32	RI	14/32
LT	7/32	RT	15/32

Fluids:

Oil
 Coolant
 Transmission
P/S Fluid Temsa / Mini
 Washer Fluid

All tires are at 115 PSI

Wash radiator, condenser N

DEF (If applicable)

Interior:

Driver Light
 Step Light
 Restroom Light
 Dash Warning Lights
 AC/Heater working
 Verify Radio,DVD,Monitors and PA are working

Undercarriage:

Fluid Leaks
Air Leaks (Use soapy water)
Wheel seals
Visual Brake inspection
Lube U-Joints, King Pins, and Gear box N
Inspect Tire wear

Part usage:


QTY: **Part Number:**

Comments:

Date: 02-09-17

Bus # 8421

Mileage: 60214

Inspector 

Date: _____

Bus ready for service: YES NO _____





Exterior:

All lights working
 Body damage
 Wipers

Fluids:

Oil
Coolant
Transmission
P/S Fluid Temsa / Mini _____
Washer Fluid

Tires:

New Spare Yes No _____
LF 16/32 RF 16/32
LO 13/32 RO 14/32
LI 14/32 RI 17/32
LT 10/32 RT 15/32

All tires are at 115 PSI

Wash radiator, condenser

DEF (If applicable)

Interior:

Driver Light
Step Light
Restroom Light
Dash Warning Lights
AC/Heater working
Verify Radio,DVD,Monitors and PA are working _____

Undercarriage:

Fluid Leaks
Air Leaks (Use soapy water)
Wheel seals
Visual Brake inspection
Lube U-Joints, King Pins, and Gear box
Inspect Tire wear

Part usage:


QTY: **Part Number:**

Comments:

Date: 01-29-17

Bus # 8421

Mileage: 59161

Inspector:  _____

Date: _____

Bus ready for service: YES NO _____



Exterior:

All lights working
 Body damage
 Wipers

Tires:

New Spare Yes No
LF 15/32 RF 15/32
LO 13/32 RO 14/32
LI 13/32 RI 14/32
LT 9/32 RT 16/32

Fluids:

Oil
Coolant
Transmission
P/S Fluid Temsa / Mini
Washer Fluid

All tires are at 115 PSI

Wash radiator, condenser N

DEF (If applicable)

Interior:

Driver Light
Step Light
Restroom Light
Dash Warning Lights
AC/Heater working
Verify Radio,DVD,Monitors and PA are working

Undercarriage:

Fluid Leaks
Air Leaks (Use soapy water)
Wheel seals
Visual Brake inspection
Lube U-Joints, King Pins, and Gear box N
Inspect Tire wear

Part usage:


QTY: Part Number:

Comments:

Date: 01-27-17

Bus # 8621

Mileage: 58459

Inspector  _____

Date: _____

Bus ready for service: YES NO



Exterior:

All lights working
 Body damage
 Wipers

Tires:

New Spare		Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
LF	15/32	RF	16/32
LO	13/32	RO	13/32
LI	13/32	RI	14/32
LT	8/32	RT	15/32

Fluids:

Oil
Coolant
Transmission
P/S Fluid Tensa /Mini
Washer Fluid

All tires are at 115 PSI
Wash radiator, condenser
DEF (If applicable)

Interior:

Driver Light
Step Light
Restroom Light
Dash Warning Lights
AC/Heater working
Verify Radio,DVD,Monitors and PA are working

Undercarriage:

Fluid Leaks
Air Leaks (Use soapy water)
Wheel seals
Visual Brake inspection
Lube U-Joints, King Pins, and Gear box
Inspect Tire wear

Part usage:


QTY: **Part Number:**

Comments:

Date: 01-26-17

Bus # 8421

Mileage: 58395

Inspected 

Date: _____

Bus ready for service: YES NO _____



Exterior:

All lights working
 Body damage
 Wipers

Tires:

New Spare Yes No
LF 14/32 RF 15/32
LO 12/32 RO 12/32
LI 12/32 RI 13/32
LT 8/32 RT 5/32

Fluids:

Oil
Coolant
Transmission
P/S Fluid Temsa/Mini
Washer Fluid

All tires are at 115 PSI

Wash radiator, condenser NO

DEF (If applicable)

Interior:

Driver Light
Step Light
Restroom Light
Dash Warning Lights
AC/Heater working
Verify Radio,DVD,Monitors and PA are working

Undercarriage:

Fluid Leaks
Air Leaks (Use soapy water)
Wheel seals
Visual Brake inspection
Lube U-Joints, King Pins, and Gear box NO
Inspect Tire wear

Part usage:

QTY: **Part Number:**

Comments:

Date: 1-25-17

Bus # 8421

Mileage: 58329.6

Inspector: 

Date: _____

Bus ready for service: YES NO



Exterior:

All lights working
 Body damage
 Wipers

Tires:

New Spare Yes No
LF 14/32 RF 15/32
LO 12/32 RO 12/32
LI 12/32 RI 12/32
LT 8/32 RT 5/32

Fluids:

Oil
Coolant
Transmission
P/S Fluid Temsa / Mini
Washer Fluid

All tires are at 115 PSI
Wash radiator, condenser NO
DEF (If applicable)

Interior:

Driver Light
Step Light
Restroom Light
Dash Warning Lights
AC/Heater working
Verify Radio,DVD,Monitors and PA are working

Undercarriage:

Fluid Leaks
Air Leaks (Use soapy water)
Wheel seals
Visual Brake inspection
Lube U-Joints, King Pins, and Gear box N/A
Inspect Tire wear

Part usage:

QTY: 7.92 **Part Number:** Gallons DEF

Comments:

Date: 1-24-17

Bus # 8421

Mileage: 58239.3

Inspector: 

Date: _____

Bus ready for service: YES NO



Exterior:

All lights working
Body damage
Wipers

Tires:

New Spare

LF 14/32
LO 12/32
LI 12/32
LT 8/32

Yes No

RF 14/32
RO 12/32
RI 12/32
RT 14/32

Fluids:

Oil
Coolant
Transmission
P/S Fluid Temsa / Mini
Washer Fluid

All tires are at 115 PSI

Wash radiator, condenser NO

DEF (If applicable)

Interior:

Driver Light
Step Light
Restroom Light
Dash Warning Lights
AC/Heater working
Verify Radio,DVD,Monitors and PA are working

Undercarriage:

Fluid Leaks
Air Leaks (Use soapy water)
Wheel seals
Visual Brake inspection
Lube U-Joints, King Pins, and Gear box NA
Inspect Tire wear

Part usage:

QTY: 6.62 **Part Number:** Galley DEF

Comments:

Need freon

Date: 1.31.17

Bus # 0421

Mileage: 59316.9

Inspector: 

Date: _____

Bus ready for service: YES NO



Exterior:

All lights working
 Body damage
 Wipers

Tires:

New Spare Yes 1 No
LF 16/32 RF 16/32
LO 14/32 RO 13/32
LI 14/32 RI 14/32
LT 8/32 RT 7/32

Fluids:

Oil
Coolant
Transmission
P/S Fluid Temsa / Mini
Washer Fluid

All tires are at 115 PSI
Wash radiator, condenser
DEF (If applicable)

Interior:

Driver Light
Step Light
Restroom Light
Dash Warning Lights
AC/Heater working
Verify Radio,DVD,Monitors and PA are working

Undercarriage:

Fluid Leaks
Air Leaks (Use soapy water)
Wheel seals
Visual Brake inspection
Lube U-Joints, King Pins, and Gear box
Inspect Tire wear

Part usage:


QTY: Part Number:

Comments:

Date: 01-22-17

Bus # 8421

Mileage: 58145

Inspector: 

Date: _____

Bus ready for service: YES NO



Exterior:

All lights working
Body damage
Wipers

Tires:

New Spare

LF 14/32
LO 12/32
LI 13/32
LT 8/32

Yes No
RF 14/32
RO 13/32
RI 13/32
RT 5/32

Fluids:

Oil
Coolant
Transmission
P/S Fluid Temsa / Mini
Washer Fluid

All tires are at 115 PSI

Wash radiator, condenser NO

DEF (If applicable)

Interior:

Driver Light
Step Light
Restroom Light
Dash Warning Lights
AC/Heater working
Verify Radio,DVD,Monitors and PA are working

Undercarriage:

Fluid Leaks
Air Leaks (Use soapy water)
Wheel seals
Visual Brake inspection
Lube U-Joints, King Pins, and Gear box N/A
Inspect Tire wear

Part usage:

QTY: Part Number:

Comments:

Date: 1-21-17

Bus # 8421

Mileage: 57900.1

Inspector: 

Date: _____

Bus ready for service: YES NO



Exterior:

All lights working
 Body damage
 Wipers

Tires:

New Spare		Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
LF	12/32	RF	16/32
LO	13/32	RO	14/32
LI	14/32	RI	14/32
LT	10/32	RT	7/32

Fluids:

Oil
 Coolant
 Transmission
P/S Fluid Temsa / Mini
Washer Fluid

All tires are at 115 PSI
Wash radiator, condenser N
DEF (If applicable)

Interior:

Driver Light
 Step Light
 Restroom Light
 Dash Warning Lights
 AC/Heater working
Verify Radio,DVD,Monitors and PA are working

Undercarriage:

Fluid Leaks
 Air Leaks (Use soapy water)
 Wheel seals
 Visual Brake inspection
Lube U-Joints, King Pins, and Gear box N
 Inspect Tire wear

Part usage:


QTY: Part Number:

Comments:

Date: 01-16-17

Bus # 8421

Mileage: 57270

Inspector 

Date: _____

Bus ready for service: YES NO _____



Exterior:

✓ All lights working
✓ Body damage
✓ Wipers

Tires:

New Spare		Yes	No
LF	15/32	RF	15/32
LO	14/32	RO	14/32
LI	14/32	RI	14/32
LT	11/32	RT	7/32

Fluids:

Oil ✓
Coolant ✓
Transmission ✓
P/S Fluid Temsa / Mini _____
Washer Fluid ✓

All tires are at 115 PSI ✓

Wash radiator, condenser ✓

DEF (If applicable) ✓

Interior:

Driver Light ✓
Step Light ✓
Restroom Light ✓
Dash Warning Lights ✓
AC/Heater working ✓
Verify Radio,DVD,Monitors and PA are working ✓

Undercarriage:

Fluid Leaks ✓
Air Leaks (Use soapy water) ✓
Wheel seals ✓
Visual Brake inspection ✓
Lube U-Joints, King Pins, and Gear box N
Inspect Tire wear ✓

Part usage:

QTY: Part Number:

Comments:

Date: 01-15-17

Bus # 8421

Mileage: 57239

Inspector: [Redacted]

Date: _____

Bus ready for service: YES ✓ NO _____



Exterior:

All lights working
 Body damage
 Wipers

Tires:

New Spare		Yes <input checked="" type="checkbox"/>	No
LF	15/32	RF	16/32
LO	14/32	RO	14/32
LI	14/32	RI	15/32
LT	9/32	RT	8/32

Fluids:

Oil
 Coolant
 Transmission
P/S Fluid Temsa / Mini _____
 Washer Fluid

All tires are at 115 PSI
Wash radiator, condenser
DEF (If applicable)

Interior:

Driver Light
 Step Light
 Restroom Light
 Dash Warning Lights
 AC/Heater working
 Verify Radio,DVD,Monitors and PA are working

Undercarriage:

Fluid Leaks
 Air Leaks (Use soapy water)
 Wheel seals
 Visual Brake inspection
Lube U-Joints, King Pins, and Gear box
 Inspect Tire wear

Part usage:

QTY: Part Number:

Comments:

Date: 01-14-17

Bus # 8421

Mileage: 57170

Inspector: 

Date: _____

Bus ready for service: YES NO _____



Exterior:

All lights working
Body damage
Wipers

Tires:

New Spare

LF 14/32
LO 12/32
LI 12/32
LT 9/32

Yes No
RF 14/32
RO 13/32
RI 14/32
RT 6/32

Fluids:

Oil
Coolant
Transmission
P/S Fluid
Washer Fluid
Temsu / Mini

All tires are at 115 PSI

Wash radiator, condenser

DEF (If applicable)

Interior:

Driver Light
Step Light
Restroom Light
Dash Warning Lights
AC/Heater working
Verify Radio,DVD,Monitors and PA are working

Undercarriage:

Fluid Leaks
Air Leaks (Use soapy water)
Wheel seals
Visual Brake inspection
Lube U-Joints, King Pins, and Gear box
Inspect Tire wear

Part usage:

QTY: 3.70
Part Number: Cooler DEF

Comments:

Date: 1-14-17

Bus # 8421

Mileage: 56975.7

Inspector: 

Date: _____

Bus ready for service: YES NO



Exterior:

All lights working
Body damage
Wipers

Tires:

New Spare

LF 14/32
LO 12/32
LI 13/32
LT 10/32

Yes No
RF 15/32
RO 12/32
RI 13/32
RT 7/32

Fluids:

Oil
Coolant
Transmission
P/S Fluid Temsa / Mini
Washer Fluid

All tires are at 115 PSI _____

Wash radiator, condenser N/A

DEF (If applicable)

Interior:

Driver Light
Step Light
Restroom Light
Dash Warning Lights
AC/Heater working
Verify Radio,DVD,Monitors and PA are working

Undercarriage:

Fluid Leaks
Air Leaks (Use soapy water)
Wheel seals
Visual Brake inspection
Lube U-Joints, King Pins, and Gear box N/A
Inspect Tire wear

Part usage:

QTY:

Part Number:

Comments:

Date: 1/12/17

Bus # 8421

Mileage: 56494.9

Inspector: 

Date: _____

Bus ready for service: YES NO _____



Exterior:

All lights working
 Body damage
 Wipers

Tires:

New Spare Yes No
LF 15/32 RF 15/32
LO 13/32 RO 14/32
LI 12/32 RI 13/32
LT 9/32 RT 6/32

Fluids:

Oil
Coolant
Transmission
P/S Fluid Temsa / Mini
Washer Fluid

All tires are at 115 PSI

Wash radiator, condenser NO

DEF (If applicable)

Interior:

Driver Light
Step Light
Restroom Light
Dash Warning Lights
AC/Heater working
Verify Radio,DVD,Monitors and PA are working

Undercarriage:

Fluid Leaks
Air Leaks (Use soapy water)
Wheel seals
Visual Brake inspection
Lube U-Joints, King Pins, and Gear box
Inspect Tire wear

E/A

Part usage:

QTY: Part Number:

Comments:

Date: 1-11-17

Bus # 8421

Mileage: 56421.0

Inspector: 

Date: _____

Bus ready for service: YES NO



Exterior:

All lights working
 Body damage
 Wipers

Tires:

New Spare
LF 15/32
LO 13/32
LI 13/32
LT 9/32
Yes No
RF 15/32
RO 12/32
RI 14/32
RT 7/32

Fluids:

Oil
Coolant
Transmission
P/S Fluid Temsa / Mini
Washer Fluid

All tires are at 115 PSI

Wash radiator, condenser NO

DEF (If applicable)

Interior:

Driver Light
Step Light
Restroom Light
Dash Warning Lights
AC/Heater working
Verify Radio,DVD,Monitors and PA are working

Undercarriage:

Fluid Leaks
Air Leaks (Use soapy water)
Wheel seals
Visual Brake inspection
Lube U-Joints, King Pins, and Gear box N/A
Inspect Tire wear

Part usage:

QTY: 7.76
Part Number: gallons DEF


Comments:

Added DEF 7.76 gallons

Date: 1/4/17

Bus # 8421

Mileage: 55298.3

Inspector 

Date: _____

Bus ready for service: YES NO