

## Motor Carrier Attachment – Echo Transportation Accident Driver PSP Report Biloxi, MS

HWY17MH010

(3 pages)

## **PSP Detailed Report**

Federal Motor Carrier Safety Administration

						Dri	iver Inf	orma	ation										
Last Name First Nam				First Name	st Name			License #					State	State					
AMBROSE LOUIS											TX								
						(	Crash /	ctiv	ity										
Crasi	Summary (C	Crashes liste	d represent	driver's invo	lvemer	nt in FMCSA-reportab	le crash	es, v	vithout a	ny dete	rminatio	n as to	responsil	oility.)					
# of Crashes: 0					# of Crashes with Fatalities: 0			# of Crashes with I			vith Injuries	: 0	0 # of Towaways:			0			
		Ī		# of Fatalities			0					of Injuries	: 0	0 # of Hazmat Releases			leases:	0	
Crasi	n Details (Cra	shes listed I	represent a d	river's involve	ment i	n FMCSA-reportable	crashes	, with	nout any	determ	ination a	s to re	sponsibili	ty.)	-				
П	Date DOT# Carrier Name			er Name		Driver Name Driver Lic S			State	Driver D	OB Rpt St Report Number Locati			Location	# Fata	# Fatalities # Injuries		ries	
						Ins	pection	n Ac	tivity								A TO U.S.	N. P.	
Inspe	ction Summa	ary					1,6745.296.			7. 100 B			Actorist Ass				Contil Lan	a George Surr	
Driver Summary						Vehicle Summary					Τ	Hazmat Summary							
Driver Inspections:						Vehicle Inspections:				1 Hazmat Inspections 0									
Driver Out-of-service Inspections: 0						Vehicle Out-of-service Inspections:					0 Hazmat Out-of-service Inspections: 0								
Driver Out-of-service Rate: 0%					0%	Vehicle Out-of-service Rate:				09	Hazmat Out-of-service Rate:				0%				
Inspe	ction Details																		
Carrier Info Drive					er Info					Inspection Info									
	Date DOT# Carrie		r Name Driver Nar		Driver Name	1 1		Driver L	ic	State [	river D	OB Rpt St	Report	Number	Hazmat	Insp L		# of Viol	
1	11/29/2012	11/29/2012 386083 WASTE MANAGEMENT OF AMI			AMBR	OSE JR, LOUIS		I			TX		TX			N	1		6

Report executed at: 8/24/2015 1:41:39 PM

MCMIS snapshot date: 07/24/2015



Vehicle	Violation:	393.209(e)	Power steering violations	NON-OOS				
Vehicle Violation: 39		393.203(c)	Hood not securely fastened					
Vehicle	Vehicle Violation: 396.3(a)(1)  Vehicle Violation: 393.55(c)(2)		Inspection, repair and maintenance of parts & accessories					
Vehicle			CMV other than truck-tractor manufactured on or after March 1, 1998 not equipped with an antilock brake system.					
Vehicle Violation: 393.47(e		393.47(e)	Clamp or Roto type brake out-of-adjustment					
Vehicle	Violation:	393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear	NON-OOS				
Violation Summar	ry							
Violation #		3. 4.	Description		# of Violations	# of Out-of-service Violations		
393.209(e)	Power stee	ring violations			1			
393.203(c)	Hood not se		1					
396.3(a)(1)	Inspection,		1					
393.55(c)(2)	CMV other	CMV other than truck-tractor manufactured on or after March 1, 1998 not equipped with an antillock brake system.						
393.47(e)	Clamp or R	Clamp or Roto type brake out-of-adjustment						
	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear							
393.53(b)	CMV manu	factured after 10/19/94	has an automatic airbrake adjustment system that fails to compensate for w	vear	1			

The summary counts and rates only include violations that were attributable to AMBROSE, LOUIS.

Lauro Unipierres Safety & Compliance Officer

Report executed at: 8/24/2015 1:41:39 PM

MCMIS snapshot date: 07/24/2015

For an explanation of FMCSA-reportable crashes see: https://www.psp.fmcsa.dot.gov/psp/FAQ.aspx.