JY JUN 28 2011

Printed on 11/19/2010 08:57

Washington Gas

LEAK SURVEY FIELD ORDER

General Information

WR No:	653896	**WR Type:**	HFI	**Quad Map:**	B017NE
Crew Assigned:	LK SUR NW				
Number of Services / Miles of Main:	299 S	3 M	**Compliance Due Date:**	21-APR-11	**Scheduled Date:** 31-MAR-11

Survey Information

Crew #	Date Surveyed	Survey Hrs.	Number of Services	Standby Hrs.	Down Time	Reason
935	6-15-11	7	124			
935	6-16-11	5	74			
935	6-17-11	7	103			
	Total	17	301	Alonzo Potts #11320		

Below Ground- Leaks Found During Survey

No	Date	Location	Grade	Description of Leak	Advised
1	6-16-11	9005 Glenville Road	3	1% on curb 10 feet east from service T	

24613

Washington Gas

LEAK SURVEY FIELD ORDER

WR NO: 653896 WORK TYPE CODE: HFI

Above Ground- Leaks Found During Survey

No	Date	Location	Grade	Description of Leak	Repaired Y / N	Meter #

Non-Leak Maintenance Found During Survey

Location	Description of Non-Leak	Priority (Check Box)				Meter #
		1 - Immediate	2 - Essential	3 - Routine	4 - Fill In	
50925 8905 Glenville Road	lower curb box to grade		✓			N/A
50926 9117 Glenville Rd	buried stop cock on riser		✓			N/A