

EVALUATION REPORT OF LIQUID PIPELINE CONSTRUCTION

Unless otherwise noted, all code references are to 49CFR Part 195. S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked
If an item is marked U, N/A, or N/C, an explanation must be included in this report.

A completed **Standard Inspection Report** is to be submitted to the Director within 60 days from completion of the inspection. A **Post Inspection Memorandum (PIM)** is to be completed and submitted to the Director within 30 days from the completion of the inspection, or series of inspections, and is to be filed as part of the **Standard Inspection Report**.

Inspection Report		Post Inspection Memorandum	
Inspector/Submit Date: 07/25/2013		Inspector/Submit Date:	
Received 08.19.13		Peer Review/Date:	
		Director Approval/Date:	
POST INSPECTION MEMORANDUM (PIM)			
Name of Operator:	Colonial Pipeline Company	OPID #:	2552
Name of Unit(s):	Fairfax Operating Unit	Unit #(s):	68361
Records Location:	Fairfax	Activity #	142286
Unit Type & Commodity:	Refined Product		
Inspection Type:	Construction I02 – short relocation	Inspection Date(s):	4/10/2013, 4/17/2013, 4/23/2013, 4/24/13, 6/12/13
PHMSA Representative(s):	James B. Fisher VASCC and Phil Sadler VASCC	AFO Days:	5

Summary:

Colonial Pipeline Company conducted an examination and re-coat of their 03 and 04 main lines in Prince William County, Virginia, prior to the installation of arch support systems for VDOT's new roadway to be installed over both pipelines. The project had originally been planned as a relocation of the lines, but both would have had to have crossed under the roadway anyway. The arch support system consisted of corrugated steel arches and linear concrete foundations for both sides of the arches. One arch approximately 400 feet long was installed for each pipeline.

Findings:

No findings

Stephen
Gliebe

Digitally signed by Stephen Gliebe
DN: cn=Stephen Gliebe, o=PHMSA,
ou=PHP-100,
email=[REDACTED]
Reason: I have reviewed this
document
Date: 2013.09.04 10:27:18 -04'00'

EVALUATION REPORT OF LIQUID PIPELINE CONSTRUCTION

Unless otherwise noted, all code references are to 49CFR Part 195. S – Satisfactory U – Unsatisfactory N/A – Not Applicable N/C – Not Checked
If an item is marked U, N/A, or N/C, an explanation must be included in this report.

Name of Operator:		Colonial Pipeline Company	
OP ID No. ⁽¹⁾	2552	Unit ID No. ⁽¹⁾	68361
HQ Address:		System/Unit Name & Address: ⁽¹⁾	
PO Box 1624 Alpharetta, GA 30009-9934		Fairfax Operating Unit 9555 Colonial Avenue Fairfax, Virginia	
Co. Official:	Mac Taylor	Activity Record ID No.:	142286
Phone No.:	██████████	Phone No.:	
Fax No.:	██████████	Fax No.:	
Emergency Phone No.:	800-926-2728	Emergency Phone No.:	
Persons Interviewed		Title	
Mike Strauss		Project Inspector	
Edward Bartee		Central Virginia Maintenance Foreman	
Raymond Martin		Martin Industries NDE Technician	
PHMSA Representative(s) ⁽¹⁾	James B. Fisher VASCC and Phil Sadler VASCC	Inspection Date(s) ⁽¹⁾	4/10/2013, 4/17/2013, 4/23/2013, 4/24/13, 6/12/13
Company System Maps (Copies for Region Files):		On file	
Description of Construction ⁽¹⁾ Company installed arch support systems for VDOT's roadway project over their 03 and 04 lines. One arch approximately 400 feet long was installed for each pipeline in Prince William County, Virginia.			

¹ Information not required if included on page 1.