

WPR18FA143
Aircraft Tools in Owners' Sailplane Trailer

These are photographs of the Owners' sailplane tool set which were found in the sailplane trailer at Avenal Gliderport several days after the accident. These photos were taken and provided to the NTSB by Mr Richard Walker, who was a colleague/friend of the pilot, and who also helped install the wings on April 27, 2018.



Figure 1 - Full Toolset

WPR18FA143
Aircraft Tools in Owners' Sailplane Trailer



Figure 2 -- Unidentified Tool



Figure 3 - Unidentified Tool

WPR18FA143
Aircraft Tools in Owners' Sailplane Trailer



Figure 4 - Unidentified Tool



Figure 5 - Unidentified Tool

WPR18FA143
Aircraft Tools in Owners' Sailplane Trailer



Figure 6 - Unidentified Tool



Figure 7 - Wrenches

WPR18FA143
Aircraft Tools in Owners' Sailplane Trailer



Figure 8 - Hex/Allen Key