



Photo 1. Mounted Specimen. Mounting material was cut before removal for SIMS analysis. The tierod hole is identified. The boxed region contains the fracture origin and the "hardened layer".