



Photo 1. N927DA on runway 17 after coming to a stop. The oil streak is visible left of the runway centerline.